

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Mister Carwash	า				
Location:		98th & Volcano)				
Site Contact Name &		Victor - Corner Stone ESC File No. K08E004					
Agency		victor@cornerstonenm.com NPDES Id. No.				NMR1002LG	
Inspection Date:				35/1050hrs			
	water Inspecto	r: Tir	mothy E. Sims				
Construction Phase: vertical							
Type of Ir	nspection: x	Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up
					_		0.1.4
Weath	er at time of i	nspection?	Clea	ır	Tempe	erature: ~	81*
Estimated	date of last s	torm 0.25" or	greater			6/1/2020	
Item	Deficiency/Corrective Action						
Number	Deficiency/ Corrective Action						
Hamber	no iccues observed all provious iccues mitigated						
	no issues observed all previous issues mitigated						
	***Please provide latest SWPPP self-inspection report.						
				1			
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	5/7/20)20
Notes:	Rlow trach ic	hecoming ent	tangled on the	nutside of th	ne nrerimete	er fence	
Notes: Blow trash is becoming entangled on the outside of the prerimeter fence.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

<u>tsims@cabq.gov</u> 06/18/20