

City of Albuquerque Stormwater Construction Site Inspection Report

	MER		General I	nformation				
ESC File No.	K09E002		Project Name:	9101 Central Ave NW				
NPDES Id. No.	NMR10		Location:		9101 Central Ave NW			
5/5	5/2025	Owner			Contractor			
Operator		Cosme Jaquez			Cosme Jaquez			
Contact na	me & title	Cosme Jaquez			Cosme Jaquez			
e-mail		jaquez.aylin14@gmail.com			jaquez.aylin14@gmail.com			
Contact Ph	Contact Phone #		505-250-7216			505-250-7216		
COA Inspector		James Hughes			start	11:30am		
Construction Phase:					thwork			
Type of Inspection:		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
	<u>er at time of i</u>				Temper	rature: ~	50	
Estimated	date of last s	storm 0.25" or greater			5/4/2025			
Item			Deficien	cy/ Correctiv	Action			
Number			Dencien	cy/ conectiv	ACTION			
1	Posting - CGP coverage was not posted too far from the Street. It isn't visible from the public							
_	road in violation of CGP 1.5. Required Mitigation: You must post a sign or other notice of							
	your permit coverage at a safe, publicly accessible location in close proximity to the							
	construction site. The notice must be located so it is visible from the public road that is							
	nearest to the active part of the construction site, and it must use a font large enough to be							
	readily viewed from a public right-of-way per CGP 1.5.							
2	The SWPPP and self-inspection reports were not available on-site during the inspection in							
	Violation of CGP 7.3, City Ordinance § 14-5-2-11(C)(1), and CGP 4.7.3. No construction							
	personnel were present at the time of inspection, and the sign indicating the location of the							
	SWPPP was missing in violation of CGP 7.3. Required Mitigation: The SWPPP, including the							
	SWPPP Map, Self-Inspection Reports, and Corrective Action Reports, must be kept up-to-date							
	per CGP 7.1 and available on-site per CGP 4.7.3, 5.4.3 and 7.3. If an on-site location is							
	unavailable to keep the SWPPP when no personnel are present, notice of the plan's location							
	must be post	ed near the	main entrance o	of your const	ruction site C	CGP 7.3.		
	BMDe The Cil	+ Fonco was o	ttached to a maki	ila ahain link f	anaa sa it waa	n't proporty instal	lad in	
3	BMPs - The Silt Fence was attached to a mobile chain-link fence, so it wasn't properly installed, in violation of CCD 2.1 and CCD 2.2.2. Bequired mitigation . The silt fance must be reset, attached to							
	violation of CGP 2.1 and CGP 2.2.3. Required mitigation: The silt fence must be reset, attached to							
	stationary stakes with the fabric embedded 12"into the ground, in accordance with the Corrective							
	Action requirements of CGP 5.2.1, no later than seven (7) calendar days from the time of discovery. If at							
	any time you find that a stormwater control needs routine Maintenance, you must immediately initiate							
	the necessary	maintenance	work and comple	te it by the cl	ose of the next	business day.		
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspec	tion Reports	requested	Latest re	port Date:	?		

Notes:	
The SWPP	PP was not available on site.

James D. Hughes