

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Nar	ne:	Westpoint 40						
Location:		98th Street & Bluewater						
Site Contact Name &				K09E041				
Agency			tandevelopment.com		Oper: I	Oper: NMR1002M/ Ownr: LEW		
Inspection Date:				00/0900hrs				
CoA Stormwater Inspector: Timothy E. Sims								
Construction Phase:					onstruction			
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up								
344 1		3	2 l		-		70*	
Weath	er at time of i	nspection? Clear			Tempe	Temperature: ~ 78*		
Estimated	date of last s	torm 0.25" or greater			6/1/2020			
Item	Deficiency/ Corrective Action							
Number	Deficiency/ Corrective Action							
1	Progress has been made with the silt fence maintenance; however, ATV's (etc) have modified							
	the intent of the perimeter sediment BMP. Please re-attach areas of the silt fence that unwelcomed							
	<u> </u>							
	visitors have modified the perimeter silt fence.							
2	Please provide either inlet protection for the four inlets on Bluewater or remove sediment from							
	the Bluewater.							
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	tion Reports	requested	Latest rep	ort Date:	6/5/2	020	
Notes:								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

06/23/20____