

## City of Albuquerque Stormwater Construction Site Inspection Report

	M E Anton		General In	formation				
ESC File No.	K09E047	7 (WO) P	roject Name:	Stockpile at 98th and I-40 @ Daytona			ona	
NPDES Id. No.	NMR1004LY		ocation:					
6/14/2024 Owner		Owner	Contractor					
Operator		98th and I-40 Land, LLC			Titan Development			
Contact name & title		Brian Patterson			Brian Patterson			
e-mail		bpatterson@titan-development.com			bpatterson@titan-development.com			
Contact Phone #		505-998-0163			505-998-0163			
COA Inspector		Chancellor English			Start/End Time: 10:30 AM			
Construe	Construction Phase:		Sto			ckpile		
Type of Ir	Type of Inspection:				Event >0.25"	311/Complaint	Follow Up	
Weath	Weather at time of i		Clea	r	Tempe		90	
	Estimated date of last storm 0.25" or greater 6/10/2024							
Item								
Number	Deficiency/ Corrective Action							
1	There has been no construction activity for over 14 days with no stabilization measures put in place in							
	violation of CO	GP Part 2.2.14.	Required mitigat	ion: Initiate	the installatio	n of stabilization	measures in	
	any areas of e	xposed soil whe	ere construction	activities hav	e permanentl	y ceased or will be	e temporarily	
	inactive for 14	or more calen	dar days per CGP	Part 2.2.14				
			, ,					
2	The owner's N	OI (98th and I-	40 Land LLC) is n	ot included i	n the SWPPP i	n violation of CGE	Part 7 2 11	
2								
	Required mitigation: Once you are authorized for coverage under the CGP, you must inc							
	your NOI submitted to the EPA along with any correspondence exchanged between you and					nd EPA		
	related to coverage under the CGP per CGP Part 7.2.11.a							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	Yes	Latest rep	oort Date:	5/28/20	)24	

Notes:	SWPPP in box attached to the back of the posting.					

City of Albuquerque Stormwater Inspector Signature and date: 6/18/2024 Contact information: Chancellor English (505) 924-3325 cenglish@cabq.gov Chance

Chancellor English