

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
ESC File No.	KO9EC				Dutch Brothers				
NPDES Id. No.	NMR10		Location:		210 98th St NE				
	8/30/2023		Owner			Contractor			
Operator		Heritage Trails Development, LLC		LC					
Contact name & title		John Caglia							
e-mail		john.caglia@dutchbros.com							
Contact Phone #		714-883-9092				1			
COA Inspector		Chancellor English		Start/End Time					
Construction Phase: Type of Inspection:		infrastructure nearly complete   Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow							
		Regular	Storm Event			311/Complaint	Follow Up		
Weath	<u>er at time of i</u>	nspection?	Clea	ar	Temper	<u>rature: ~</u>	85		
Estimated	date of last s	torm 0.25"	or greater			8/8/2023			
Item			Deficien	ou/Correctio	a Astion				
Number			Dencient	cy/ Correctiv	e Action				
1	The normit co	vorago postir		alation of CC	D Dart 1 E Doc	wirod mitigation	Vou must		
1	The permit coverage posting was missing in violation of CGP Part 1.5. Required mitigation: You must post a sign or other notice of your permit coverage at a safe, publicly accessible location in close proximity to the construction site per CGP Part 1.5.								
2	2 The SWPPP and inspection reports were unavailable for the inspection in violation of CGP Parts and 7.3. Construction equipment stored and land disturbance off-site that is not marked on the						°arts 4.7.3		
							n the ESC		
	Plan map submitted to the city in violation of CGP Part 7.2.4. Required mitigation: You must keep a								
	•	current copy of your SWPPP and all inspection reports at the site or at an easily accessible location so							
	that it can be made available at the time of an on-site inspection per CGP Parts 4.7.3 and 7.3. The site map must include locations of on-site and off-site construction support activities per CGP Part 7.2.4.b.v.								
	map must incl	ude locations	s of on-site and off-	site construc	tion support a	ctivities per CGP P	'art 7.2.4.b.vii.		
3	The are multir	ole gaps in the	e perimeter silt fen	ce in violatior	of CGP Parts	2.1.2 and 2.1.4. F	Required		
	The are multiple gaps in the perimeter silt fence in violation of CGP Parts 2.1.2 and 2.1.4. Required mitigation: You must design and install all stormwater controls in accordance with good engineering								
	-	-				-			
	•	• • •	ble design specifica	•					
	controls are maintained and remain in effective operating condition during permit coverage and are								
	protected from activities that would reduce their effectiveness.								
2.1	Discharge off site?	(Y/N)	no						
4	Self Inspec	tion Reports	5 No	Latest re	port Date:	N/A	l.		

Notes:		

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Chancellor English (505) 924-3325 cenglish@cabq.gov