

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No. K09E					98th and Central Warehouse			
NPDES Id. No. NMR10		0065E L	5E Location:		9561 Central Ave NW			
	19/2024	Owner			Contractor			
Operator			al Partners LLC					
Contact na	me & title	Alfredo Barrenechea						
e-mail		alfredo@go-absolute.net						
Contact Phone #		505-246-6006				1		
COA Inspector		Chancellor	English		Start/End Time	130	om	
Construction Phase:			lo. 5 .1		nding	lass to the	I= 11	
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weather at time of inspection? Clear Temperature: ~ 50							50	
Estimated	date of last s	torm 0.25" o	r greater			11/7/2024		
Item	Deficiency/ Corrective Astics							
Number	Deficiency/ Corrective Action							
	The CM/DDD and	The CM/DDD and self-inequation repeated was a self-black thank.						
1	The SWPPP and self-inspection reports were not available at the time of the on-site inspection in violation of CGP Parts 4.7.3 and 7.3. Required mitigation: You must keep a current copy of your SWPPP and all self-inspection reports at the site or at an easily accessible location so that it can be							
							=	
							it can be	
	made available at the time of an on-site inspection per CGP Parts 4.7.3 and 7.3.							
2	Sediment has been tracked-out and is discharging onto the Central Ave NW access road in violation of							
_	CGP Part 2.2.4. Required mitigation: Minimize sediment track-out by a) restricting vehicle use to							
	properly designated exit points, b) using appropriate stabilization techniques at all points that exit							
		•		= '		-		
	=		=			ssary to ensure th		
		=	· ·			cked-out from yo		
	remove the de	eposited sedin	nent by the end o	of the same bu	ısiness day in v	which the track-o	ut occurs or	
	by the end of	the next busin	ess day if track-o	ut occurs on a	non-busines	s day. Remove th	ne track-out	
	by sweeping, s	shoveling, or v	acuuming these	surfaces, or by	using other s	imilarly effective	means of	
		_	_		_	out sediment int		
						ng water per CGP		
	constructed of	i ilaturai site u	irairiage reature,	storm drain ii	net, or receiving	ilg water per cur	rait 2.2.4	
3	3 BMPs - The perimeter silt fence has some damage and is not preventing sediment discha construction exit has no track-out measures in place in violation of CGP Parts 2.1.3 and 2					sediment dischar	ge, and the	
	mitigation: Complete installation of stormwater controls by the time each phase of constru				•			
	_	•			•	ny given portion (		
					=			
	_	· · · · · · · · · · · · · · · · · · ·		_		s (e.g., buffers, p		
	-			•		scharges from the		
	clearing, gradi	ng, excavating	g, and other earth	n-disturbing a	ctivities. Ensu	re that all stormw	ater controls	
	are maintaine	d and remain i	in effective opera	iting condition	n during permi	it coverage and a	re protected	
	from activities	that would re	duce their effect	iveness per C	GP Part 2.1.4			
				•				
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	No	Latest rer	ort Date:	N/A		
	Jen mapee	Neports	140	Latestie	Join Duice.	11/	•	

Notes:	
The postin	g was attached to the gate at the construction exit. While the gate is open, the posting is
viewable f	rom the road, but if the gates are closed, the posting is not viewable. Please find a new
location fo	or the posting so that it can be viewed at all times.

City of Albuquerque Stormwater Inspector Signature and date:

11/20/2024

Chancellor English

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov