

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Name:		Vitality Works						
Location:		8500 Bluewater NW						
Site Contact Name & Agency		Insight Constr	uction	ESC File No.		K10E009		
		Daniel Reeves		NPDES Id. No.		NMR100182		
Inspection			tart/End Time: 09	30/0935hrs				
	water Inspecto							
	tion Phase:				ilized		_	
Type of Ir	spection: X	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up	
\A/ 1 l.			Class		T		F4.¥	
Weather at time of inspection? Clear Temperature: ~ 51*								
Has there been a storm event since site was Permitted? Clarify amount: (i.e <1/4" to >3/4"): yes, >1/4"								
Item	Deficiency/ Corrective Action							
Number	Deficiency, corrective Action							
	SITE IS STABILIZED							
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	tion Reports	N/A	Latest rep	ort Date:	03.29.2	19	
Notes: (City		•	ice can be left blank	-				
1	Construction Ge	•		<b></b>				
			- /					
Maintena	nce or correct	tive actions a	re to be comple	ted within s	even (7) day	ys.		
Notes:								
City of Albuquerque Stormwater Inspector Signature and date:								
Contact information: Timothy Sims, 505-803-6155 or								

tsims@cabq.gov

04/18/19