

City of Albuquerque Stormwater Construction Site Inspection Report

General Information						
Project Nar	ne:	Defined Fitness @ Unser Crossings				
Location:		Unser & Central				
Site Contact Name & Agency		Joseph - Bla	anchard Properties	ESC File No.	K10E045B	
		rjones@jo	nescpa.com	NPDES Id. No.	NMR1001X7	
Inspection Date:		06/04/19		'50/0830hrs		
	vater Inspecto	r:	Timothy E. Sims			
Construction Phase:					and plumbing	
Type of In	spection:	Regular	Storm Event	Post Storm I	Event >0.25" 311/Complaint x Follow U	ე
347 -1		3				
Weathe	er at time of i	nspection?	Clea	ar	Temperature: ~ 63*	
Estimated	nated date of last storm 0.25" or greater 5/11/2019					
Item	Deficiency/ Corrective Action					
Number	Deficiency/ Corrective Action					
1	Please provide the latest self-inspection report					
2	Perimeter silt fence require maintenance. Sediment build up exceedes 50% in some areas and					
_	some sections are down. Please re-install and remove sediment in these areas.					
3	This mornings washout from concrete pumping requires cleaning.					
4	concrete washout facility requires maintenance. It if full.					
	, , , , , , , , , , , , , , , , , , , ,					
						_
						_
						_
						_
						_
						_
						_
						_
						_
						_
2.1	Discharge off site?	(Y/N)	No			
4	Self Inspect	ion Report	requested	Latest rep	port Date:	
					<u> </u>	
Notes:						
						\neg
						-

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

06/04/19____