

City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation		
Project Name: Generations			s @ West Mesa			
Location:		5710 Avalo	n Rd NW			
Site Con	tact Name &	Joe Cocchin	a/ Ben Marshal	ESC File No.	K11E084	
A	gency	Gorman Co	mpany Inc.	NPDES Id. No.		
Inspection	n Date:	03/11/19	Start/End Time: 10	045/1100hrs		
CoA Storr	nwater Inspe	ctor:	10 SW -	Timothy Sims	s, Stormwater Inspector	
Preser	nt Phase of	e of verticle with some utilities				
Cons	truction:					
					to Councillato	
Type of I	nspection:	Regular	Storm Event	Post Storm Ev	vent >0.25" 311/Complaint	x Follow Up
				_		
Weath	er at time of	inspection?			Temperature: ~	46*
	e 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rain		L		
			nce site was Per			_ 7.561
Clarify am	nount: (i.e <1	1/4" to >3/4"			>3/4"	
				ection		
			Maintenance			
CGP	BMP / Activity		or Corrective		Location and Notes	
Section			Action Required			
1.5	Post a	Notice	Required			
1.5	Provide and maintain Natural buffer when			 	STANDARD RESIDENCE TO SEE	
2.2.1	Waters of the US <50ft.					
2.2.3	Sediment control al	ong any perimeter				
2.2.3	Sediment control al	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control ald	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control ald	ong any perimeter			211 211 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
2.2.3	Sediment control ald	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter			4	
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control alo	ong any perimeter				
2.2.3	Sediment control ald	ong any perimeter				
2.2.4	Minimize sediment track out					

Manage stock piles			
minimize dust			
Protect storm drain inlets			
Protect storm drain inlets			ii ii
Minimize erosion of conveyance channels			
Sediment Basins			
Stabilize exposed portions of the site			
Stabilize exposed portions of the site			
Stabilize exposed portions of the site			
Stabilize exposed portions of the site		777 1 2	
Equipment and vehicle fueling			
Equipment and vehicle washing			
Building material storage			
Fuel, oil, hydraulic fluid, petroleum products and chemical storage			*
Construction and domestic wastes			
Construction and domestic wastes			
Washing applicators used for paint, stucco, concrete, etc.			
stucco, concrete, etc.			
Washing applicators used for paint, stucco, concrete, etc.			
Dewatering			
Discharge off site? (Y/N)	No		
Self Inspection Reports	requested	Latest report Date:	
	minimize dust Protect storm drain inlets Protect storm drain inlets Minimize erosion of conveyance channels Sediment Basins Stabilize exposed portions of the site Equipment and vehicle fueling Equipment and vehicle washing Building material storage Fuel, oil, hydraulic fluid, petroleum products and chemical storage Construction and domestic wastes Construction and domestic wastes Washing applicators used for paint, stucco, concrete, etc. Washing applicators used for paint, stucco, concrete, etc. Dewatering Discharge off site? (Y/N)	minimize dust Protect storm drain inlets Protect storm drain inlets Minimize erosion of conveyance channels Sediment Basins Stabilize exposed portions of the site Equipment and vehicle fueling Equipment and vehicle washing Building material storage Fuel, oil, hydraulic fluid, petroleum products and chemical storage Construction and domestic wastes Construction and domestic wastes Washing applicators used for paint, stucco, concrete, etc. Washing applicators used for paint, stucco, concrete, etc. Dewatering Discharge off site? (Y/N)	minimize dust Protect storm drain inlets Protect storm drain inlets Minimize erosion of conveyance channels Sediment Basins Stabilize exposed portions of the site Equipment and vehicle fueling Equipment and vehicle washing Building material storage Fuel, oil, hydraulic fluid, petroleum products and chemical storage Construction and domestic wastes Washing applicators used for paint, stucco, concrete, etc. Washing applicators used for paint, stucco, concrete, etc. Washing applicators used for paint, stucco, concrete, etc. Dewatering Discharge off site? (Y/N)

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	Please provide me the most current self-inspection report

Timothy F. Sims Digitally signed by Timothy E. Sims DN: cn=Timothy E. Sims, o=Stormwater Inspectionos,

City of Albuquerque Stormwater Inspector Signature and date: E. Sims

3/11/2019

Contact information:

Timothy Sims, 505-803-6155 or

tsims@cabq.gov

Construction General Permit (CGP)



City of Albuquerque Stormwater Construction Site Inspection Report

			General In	formation			
Project Name: Generations @ West N			@ West Mesa				
Location:		5710 Avalor	n Rd NW				
Site Cont	act Name &	Joe Cocchin	a/ Ben Marshall	ESC File No.	K11E084		
Αį	gency	Gorman Cor	mpany Inc.	NPDES Id. No.			
Inspection Date: 03/18/19 Sta		tart/End Time: 09	10/0930hrs				
	nwater Inspec	ctor:	1	Timothy Sim	s, Stormwater Inspector		
Presen	t Phase of		V	erticle with s	some utilities		
Cons	truction:						
Type of Ir	spection:	Regular	Storm Event	Post Storm E	vent >0.25" 311/Complaint x Follow Up		
Weath	er at time of i	nspection?			Temperature: ~ 49*		
		Clear					
Has th	ere been a st	orm event sii	nce site was Peri				
Clarify am	ount: (i.e <1	./4" to >3/4")	:	yes,	>3/4"		
			Inspe	ction			
		1017	Maintenance				
ccn	BMP / Activity		or Corrective		Location and Notes		
CGP			Action		AMERICAN MARKET CONTRACTOR		
Section			Required				
1.5 Post a Notice Provide and maintain Natural buffer when							
2.2.1	Waters of the US <50ft.	aturar burier when					
2.2.3	Sediment control alc	ong any perimeter	х	s	weep Avalon and 58th Street		
2.2.3	Sediment control alc	ong any perimeter					
2.2.3	Sediment control alo	ong any perimeter					
2.2.3	Sediment control alc	ong any perimeter					
2.2.3	Sediment control ald	ong any perimeter					
2.2.3	Sediment control alo	ong any perimeter					
2.2.3	Sediment control alo	ong any perimeter					
2.2.3	Sediment control alo	ong any perimeter					
2.2.3	Sediment control alo	ong any perimeter					
2.2.3	Sediment control alo	ong any perimeter					
2.2.3	Sediment control alc	ong any perimeter					
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control alc	ong any perimeter					
2.2.3	Sediment control alc	ong any perimeter					
2.2.3	Sediment control along any perimeter						
2.2.3	Sediment control alc	ong any perimeter					
2.2.3	Sediment control alc	ong any perimeter					
2.2.4	Minimize sediment track out						

2.2.5	Manage stock piles			
2.2.6	minimize dust			
2.2.10	Protect storm drain inlets			
2.2.10	Protect storm drain inlets			
2.2.11	Minimize erosion of conveyance channels		==	
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.2.14	Stabilize exposed portions of the site			
2.3.1	Equipment and vehicle fueling			
2.3.2	Equipment and vehicle washing			
2.3.3	Building material storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and domestic wastes			
2.3.3	Construction and domestic wastes			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	3/6/2019

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	continue nightly sweeping of Avalon and 58th Street

Timothy E. Sims

Digitally signed by Timothy E. Sims
DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, ouu=Planning, email=tsims@cabq.gov, c=US
Date: 2019.03.18 09:42:04 -06'00'

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Timothy Sims, 505-803-6155 or

tsims@cabq.gov

3/18/2019

Construction General Permit (CGP)

Sims, Timothy E.

From:

Sims, Timothy E.

Sent:

Monday, March 18, 2019 9:44 AM

To:

'Joe Cocchia'

Cc:

Gregg Burke; Bill Cauthen; Sims, Timothy E.

Subject:

RE: SWPPP Inspection: Gorman for Generations West 03/07/19

Attachments:

03.18.19F_K11E804F.InspectionS.pdf

Joe,

Thanks for the self-inspection reports. No issues witnessed today; please continue sweeping Avalon Rd and 58th Street as needed.

Thanks,



Timothy Sims

Stormwater Inspector stormwater quality o 505.803.6155 e tsims@cabq.gov cabq.gov/planning

From: Joe Cocchia [mailto:jcocchia@gormanusa.com]

Sent: Monday, March 11, 2019 2:40 PM **To:** Sims, Timothy E. <tsims@cabq.gov>

Cc: Gregg Burke <gburke@gormanusa.com>; Bill Cauthen <bcauthen@gormanusa.com>

Subject: FW: SWPPP Inspection: Gorman for Generations West 03/07/19

Timothy,

Please see attached, we are not doing self-inspections, we have Inspections plus.

Thank you,

Joe Cocchia

Site Superintendent



P 505-730-4475

E jcocchia@gormanusa.com W https://ddei3-0-

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=www.gormanusa.com&umid=CD8E965A-83D7-8905-AA8B-EC6B6E90FDA4&auth=f0ebcd052f61e7a39dc93191e8a01d02608499af-2f9c8367678ad0c3f0bee17b8d4378df4400c020









From: Gregg Burke <gburke@gormanusa.com>

Sent: Monday, March 11, 2019 1:23 PM To: Joe Cocchia < jcocchia@gormanusa.com>

Subject: FW: SWPPP Inspection: Gorman for Generations West 03/07/19

From Friday.

gb

From: Jeff Hart < Jeffdh@inspectionsplusinc.com>

Sent: Friday, March 8, 2019 2:30 PM

To: Gregg Burke <gburke@gormanusa.com>

Cc: 'Shane Gibbs' < Bookkeeping@inspectionsplusinc.com'>; inspectionsplusjeff@gmail.com

Subject: SWPPP Inspection: Gorman for Generations West 03/07/19

Thank you.

Have a great weekend.

Please let me know if I can assist with anything.

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Monday, February 25, 2019 7:41 AM

To: 'gburke@gormanusa.com' <gburke@gormanusa.com>

Cc: 'Shane Gibbs' <Bookkeeping@inspectionsplusinc.com'; 'inspectionsplusieff@gmail.com'

<inspectionsplusjeff@gmail.com>

Subject: FW: SWPPP Inspection: Gorman for Generations West 02/20/19

Thank you.

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office

NPDES FORM 3510-9

County or Similar Government Subdivision: BERNAULLO

Latitude/Longitude: 35.084°N, 106.7019°W

\$EPA

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY WASHINGTON, DC 20460 NOTICE OF INTENT (NOI) FOR THE 2017 NPDES CONSTRUCTION PERMIT

FORM Approved OMB No. 2040-0004

Submission of this Notice of Intent (NOI) constitutes notice that the operator identified in Section III of this form requests authorization to discharge pursuant to the NPDES Construction General Permit (CGP) permit number identified in Section III of this form. Submission of this NOI also constitutes notice that the operator identified in Section III of this form meets the eligibility requirements of Part 1.1 CGP for the project identified in Section IV of this form. Permit coverage is required prior to commencement of construction activity until you are eligible to reminate coverage as detailed in Part 8 of the CGP. To obtain authorization, you must submit a complete and accurate NOI form. Discharges are not authorized if your NOI is incomplete or inaccurate are eligible to permit coverage. Refer to the instructions at the end of this form.

and accurate NOI form. Discharges are not authorized if your NOI is incor	mplete or inaccurate or if you were never eligible for per	mit coverage. Refer to the instructions at the end of this form.	
Permit Information			
NPDES ID: NMR1001GG			
State where your construction site is located: NM			
Is your construction site located on Indian Country Lands?	DYES & NO		
Are you requesting coverage under this NOI as a *Federal Operato _definitions_508.pdf)?	or"as defined in Appendix A (https://www.epa.gov/si	tes/production/files/2017-02/documents/2017_cgp_final_appendix_a	
DYES & NO			
Have stormwater discharges from your current construction site b	peen covered previously under an NPDES permit?	□YES ⊗NO	
Will you use polymers, flocculants, or other treatment chemicals a	at your construction site? ☐ YES		
Has a Stormwater Pollution Prevention Plan (SWPPP) been prepare	red in advance of filling this NOI, as required?	&YES ONO	
Are you able to demonstrate that you meet one of the criteria lister _endangered_species_reqs_508.pdf) with respect to protection of ☑ YES ☐ NO	d in Appendix D (https://www.epa.gov/sites/producti threatened or endangered species listed under the	ion/files/2017-02/documents/2017_cgp_final_appendix_d Endangered Species Act (ESA) and federally designated critical habitat?	
8123 510			
Have you completed the screening process in Appendix E (https://protection of historic properties?	/www.epa.gov/sites/production/files/2017-02/docume	ents/2017_cgp_final_appendix_ehistoric_properties_reqs_508.pdf) rel	ating to the
discharges not expressly authorized in this permit cannot become permit via any means, Including the Notice of Intent (NOI) to be co	e authorized or shielded from liability under CWAs overed by the permit, the Stormwater Pollution Prev	Part 1,2.1 and the allowable non-stormwater discharges listed in Part 1. ection 402(k) by disclosure to EPA state or local authorities after Issuan ention Plan (SWPPP), during an Inspection, etc. If any discharges requi ill be discharged, they must be covered under another NPDES permit.	ice of this
Operator Information			
Operator Information			
Operator Name: Generations at West Mesa, LLC.			

Mailing Address: Street/Location: 200 N Main St			
	<u>z</u> w_	71- 0-1- 57575	
City: Oregon	State: AM	Zip Code: 53575	
County or Similar Government Subdivision: DANE			
Operator Point of Contact Information			
First Name, Middle Initial, LastName: Tom Jones			
Title: Project Manager			
Phone: 608-835-3900	Ext.		
Email: ljones@gormanusa.com			
Project/Site Information			
Project/Site Name: Generations at West Mesa			
Project/Site Address			
Street/Location: Avalon Rd NW at 57th St NW			
City: Albuquerque	State: NM	Zip Code: 87105	

Latitude/Longitude Data Source: Google Earth

Horizontal Reference Datum: NAD 83

Project Start Date: 08/06/2018

Project End Date: 08/31/2019

Estimated Area to be Disturbed: 3.75

Types of Construction Sites:

Commercial

Will there be demolition of any structure built or renovated before January 1, 1980?

□YES ☑ NO

Was the pre-development land use used for agriculture?

DYES WNO

Have earth-disturbing activities commenced on your project/site?

DYES ENO

Is your project located on a property of religious or cultural significance to an Indian tribe?

OYES ENO

Discharge Information

Does your project/site discharge stormwater into a Municipal Separate Storm Sewer System (MS4)?

EYES DNO

Are there any waters of the U.S. within 50 feet of your project's earth disturbances?

OYES ENO

Are any of the waters of the U.S. to which you discharge designated by the state or tribal authority under its antidegradation policy as a Tier 2 (or Tier 2.5) water (water quality exceeds levels necessary to support propagation of fish, shellfish, and wildlife and recreation in and on the water) or as a Tier 3 water (Outstanding National Resource Water)? See Appendix F (https://www.epa.gov/sites/production/files/2017-02/documents/2017_ogp_final_appendix_f_-tier_3_tier_2_and_tier_2.5_waters_508.pdf)

EYES ONO

001: Rio Grande

Latitude/Longitude: 35.0891°N, 106.682°W

Tier Designation: Tier 2

Is this receiving water impaired (on the CWA 303(d) list)?

EYES DNO

Has a TMDL been completed for this receiving waterbody?

EYES □NO

Pollutant

Causing Impairment?

TMDL ID

TMDL Name

E coli

Yes

38855

Rio Grande River 2105_50 E. coli TMDL

PCB in fish tissue

Yes

Oxygen, dissolved percent saturation

Yes

Stormwater Pollution Prevention Plan (SWPPP)

First Name, Middle Initial, LastName: Cassandra

Durkin

Title: CESSWI, SWPPP Compliance Manager

Phone: 505-344-9410

Ext

Email: cassandra@nspectionsplusinc.com

Endangered Species Protection

Using the Instructions in Appendix D of the CGP, under which criterion listed in Appendix D are you eligible for coverage under this permit? Criterion A

Provide a brief summary of the basis for criterion selection listed above (the necessary content for a supportive basis statement is provided under the criterion you selected.):

Communication with USFWS states that there are no Critical Habitats within the project area.

Historic Preservation

Are you installing any stormwater controls as described in Appendix E (https://www.epa.gov/sites/production/files/2017-02/documents/2017_cgp_final_appendix_e_-historic_properties_reqs_508.pdf) that require subsurface earth disturbances? (Appendix E (https://www.epa.gov/sites/production/files/2017-02/documents/2017_cgp_final_appendix_e__historic_properties_reqs_508.pdf), Step 1)

© YES © NO

		,	

Have prior surveys or evaluations conducted on the site already determined historic properties do not exist, or that prior disturbances have precluded the existence of historic properties? (Appendix (https://www.epa.gov/sites/production/files/2017-02/documents/2017_cgp_final_appendix_e_-_historic_properties_reqs_508.pdf), Step 2):

EYES DNO

Certification Information

Certified By: Ron Swiggum (GORMANGC18)

Certified On: 07/17/2018 12:29 PM

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel property gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I have no personal knowledge that the information submitted is other than true, accurate, and complete, an aware that there are significant penaltics for submitting false information, including the pessibility of fine and imprisonment to knowing violations. Signing an accuration document on behalf of another person is subject to criminal, civil, administrative, or other lawful action. Centra Chine 5-0-19

KIIE084

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Monday, February 11, 2019 5:34 AM

To: 'gburke@gormanusa.com' <gburke@gormanusa.com>

Cc: 'Shane Gibbs' <Bookkeeping@inspectionsplusinc.com'>; 'inspectionsplusjeff@gmail.com'

<inspectionsplusjeff@gmail.com>

Subject: SWPPP Inspection: Gorman for Generations West 02/05/19

Thank you.

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Monday, January 28, 2019 1:41 PM

To: 'gburke@gormanusa.com' <gburke@gormanusa.com'>; 'tjones@gormanusa.com' <tjones@gormanusa.com'>

Cc: 'Shane Gibbs' <Bookkeeping@inspectionsplusinc.com>; 'inspectionsplusjeff@gmail.com'

<inspectionsplusjeff@gmail.com>

Subject: SWPPP Inspection: Gorman for Generations West 01/22/19

Thank you.

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Friday, January 11, 2019 3:45 PM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 01/08/19

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office 505-379-7626 **From:** Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Tuesday, January 1, 2019 6:09 AM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 12/26/18

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Tuesday, December 11, 2018 3:21 PM

To: 'gburke@gormanusa.com'

Cc: 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 12/11/18

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office

505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Friday, November 30, 2018 3:10 PM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 11/27/18

Thank you.

Have a great weekend.

Jeff D. Hart Inspections Plus Inc. 805 Nikanda Rd. NE Albuquerque, NM. 87107 505-344-9410 Office 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Thursday, November 15, 2018 3:26 PM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 11/13/18

Thank you.

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Friday, November 2, 2018 10:25 AM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 10/30/18

I apologize for the delay.

Please let me know if you have any questions or concerns.

Thank you.

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hant [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Friday, October 19, 2018 1:15 PM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 10/16/18

Thank you.

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Wednesday, October 3, 2018 4:46 AM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com'

Cc: 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 10/02/18

Good morning,

We can resume the "dry season" inspection frequency of every 14 days. The next site visit will be on October 16th.

Thank you.

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Thursday, September 27, 2018 12:04 PM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 09/25/18

Thank you.

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Sunday, September 23, 2018 5:53 AM

To: 'gburke@gormanusa.com'; 'tjones@gormanusa.com' **Cc:** 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP RAIN Inspection: Gorman for Generations West 09/20/18

Good morning Mr. Burke,

Please let me know if you have any questions or concerns. We have just one week left of the monsoon and we will move to 14 day inspections.

Thank you.

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Wednesday, September 19, 2018 5:30 AM

To: 'tjones@gormanusa.com'

Cc: 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 09/18/18

Thank you.

Jeff Hart

Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Thursday, September 13, 2018 6:12 AM

To: 'tjones@gormanusa.com'

Cc: 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: FW: SWPPP Inspection: Gorman for Generations West 09/11/18

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Wednesday, September 5, 2018 11:35 AM

To: 'tjones@gormanusa.com'

Cc: 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 09/04/18

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Wednesday, August 29, 2018 2:03 PM

To: 'tjones@gormanusa.com'

Cc: 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: FW: SWPPP Inspection: Gorman for Generations West 08/28/18

Jeff Hart Inspections Plus, Inc. 505-379-7626

From: Jeff Hart [mailto:Jeffdh@inspectionsplusinc.com]

Sent: Thursday, August 16, 2018 5:43 AM

To: 'tjones@gormanusa.com'

Cc: 'Shane Gibbs'; 'inspectionsplusjeff@gmail.com'

Subject: SWPPP Inspection: Gorman for Generations West 08/14/18

Thank you for your time. Please let me know if you have questions or concerns.

Jeff Hart Inspections Plus, Inc. 505-379-7626

This message has been analyzed by Deep Discovery Email Inspector.

Sims, Timothy E.

From:

Sims, Timothy E.

Sent:

Monday, March 11, 2019 1:09 PM

To:

'Joe Cocchia'; Ben Marshall

Cc:

Bill Cauthen; Gregg Burke

Subject:

RE: K11E084 - Generations @ West Mesa

Attachments:

03.11.19_K11E804F.InspectionS.pdf

Joe,

Thanks for addressing all of the issues, please provide me the most current self-inspection report.

Thanks,

Timothy Sims
Stormwater Inspector
stormwater quality
o 505.803.6155
e tsims@cabq.gov
cabq.gov/planning

----Original Message-----

From: Joe Cocchia [mailto:jcocchia@gormanusa.com]

Sent: Friday, February 15, 2019 1:21 PM

Subject: Re: K11E084 - Generations @ West Mesa

Timothy

Thanks for your site visit, sorry I couldn't spend with you, pesky meeting.

We will address your concerns immediately.

Thanks

Joe

Sent from my T-Mobile 4G LTE device

----- Original message-----

From: Sims, Timothy E.

Date: Fri, Feb 15, 2019 1:12 PM To: Joe Cocchia; Ben Marshall;

Cc: Sims, Timothy E.;

Subject:K11E084 - Generations @ West Mesa

Joe,

Thanks for meeting with me today, my apologies for the timing; for the size of the site all seems to function well. A few issues noted during my inspection:

- 1. Provide a sediment BMP at the east entrance on 57th St and Esperanza. Some soil may require grading in this area.
- 2. Track out from this area has migrated down Esperanza and to Central on 57th St.-Please clean 57th St to Central and Esperance of sediment.

 Thanks,

[one albuquerque]

Timothy Sims
Stormwater Inspector
stormwater quality
o 505.803.6155
e tsims@cabq.gov<mailto:tsims@cabq.gov>
cabq.gov/planning

This message has been analyzed by Deep Discovery Email Inspector.

Development & Commercial Stormwater Construction Site Inspection Report

	well-the transfer of the trans					
	General Info	ormation				
Project Name	Generations at West Mesa					
Owners/Operators Name	Gorman General Contra	ctors, LLC.				
Date of Inspection	03/06/19	Start Time	15:30			
Inspector's Name(s)	Jeff D. Hart					
Inspector's Title(s)	Inspector.					
Inspector's Contact Information	Jeffdh@inspectionsplusi					
Inspector's Qualifications	Training and work experience – see inspector qualification page in section 2 of the SWPPP.					
Type of Inspection: ☐ Regular ☐ During storm e	vent Post-storm eve	ent				
	Weather Infe	ormation				
Has there been a storm event since the last inspection? Yes If yes, provide: Storm Start Date: 02/22/19=0.07"; 02/23/19= Trace Approximate Amount of Precipitation (in): <0.10" Cumulative events per Weather Underground: Yucca Flats NM KNMALBUQ712 Weather at time of this inspection? Clear Cloudy Rain Sleet Snowing High Winds Partly Cloudy						
Have any discharges occurred since the last inspection? No If yes, describe: What did the water look like at the time of the discharge? Clear Partly turbid Very turbid Are there any discharges at the time of inspection? No If yes, describe: What did the water look like at the time of the discharge? Clear Partly turbid Very turbid						
 Is a rain gauge installed on site? No Where is it located? Weather Underground: Yucca Flats NM KNMALBUQ712 Has the Rain Event page been filled out? No Inspectors log updated. Are there MSDS sheets on site? Yes Where are they located? Construction trailer. Has the SWPPP been signed on the certification page? No What companies have signed? GormanG.C Have the delegation letters been signed? No What companies have signed? Gorman G.C Has a delegation of authority been filled out for who is signing the inspection reports? No Who is signing the inspection reports? Tom Jones. Has the "Chemical On Site" form been filled out? Yes Construction trailer. Is there a spill kit on site? Yes Where is it located? Construction trailer. Have they done any training for the supervisors or others? Yes Was the inspector able to train any one on this visit? No Who did you speak with? Tom. 						
Are the SWPPP and inspections available on site?	Yes The SWPPP	book and inspection	ons are located at Construction trailer.			
Notas						
Notes 1. "Weighted" wattle at fence base on 57th street and Esperanza. Removed and replaced around tie-in work. Continue to monitor replacement of wattle and sweeping of sidewalk if necessary. 2. 3.						

	Final Stat	oilization/Termina	tion Checklist.
1.	Are all soil-disturbing activities complete?	No	
2.	Have all inactive areas of the site not covered by pavement or structure achieved a density of 70% coverage?	No	
3. Date of Final Stabilization.			
	If construction ceases on the site for more the	han 14 days, the sit	e must be stabilized until construction resumes.
Date	e Construction Stopped	Date Construction	n Resumed
Mea the	sures Taken to Stabilize Site.		

Construction Phasing		
Activity	Current Status	Activity Started / Completed
Installed BMPs	Complete	Started: 08/14/18
		Completed:
Site Clearing and Grading	In progress.	Started: 08/14/18
		Completed:
Installing Utilities	In progress.	Started: 08/28/18
		Completed:
Building Structure	In progress by bldg. letter.	Started: 09/01/18
		Completed:
Paving and Walks		Started:
		Completed:
Final Grading/ Stabilize Site		Started:
		Completed:
Other	Utility work in progress on 57 th	Started: 01/08/19
		Completed: 01/22/19

Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log.

	List of BMPs Installed	BMP Installed?	BMP Maintenance Required?	Notes
1	Block Wall	Yes	No	
2	Wattles	Yes	No	
3	Portable Toilet	Yes	No	
4	Silt Fence	Yes	No	
5	Stabilized Construction Er	Yes	No	
6	Staging Area	Yes	No	
7	Swale	Yes	No	
8	Cut-back at Curb	Yes	No	
9	Inlet Protection	Yes	No	
10	Concrete Washout	Yes	No	

Ver 092314

Date: 03/06/19

Project:

Gorman Contractors for Generations West.

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
01	BMP's in place prior to earth disturbing activities. No site corrective actions noted at the time of inspection.	08/14/18		08/14/18
02	Maintain inlet at 57 th and Avalon: Clear sediment, repair wattle and coco mat.	08/28/18		09/04/18
03	Post NOI at construction entrance.	08/28/18		09/04/18
04	No additional site BMP corrective actions noted at the time of inspection.	09/04/18		09/04/18
05	No additional site BMP corrective actions noted at the time of inspection. Sediment built up at inlet on 57 street caused by AUI from uphill slope.	09/11/18		09/11/18
06	No additional site BMP corrective actions noted at the time of inspection.	09/18/18		09/18/18
O7 Add rock to trackout pad to prevent sediment transfer to street, continue to sweep exit.		09/25/18		10/02/18
08	No additional site BMP corrective actions noted at the time of inspection. Active work to remove stockpile from North east corner.	10/02/18		10/02/18
09	Sweep construction exit, sediment transfer to roadway.	10/16/18	10/18/18	10/30/18
10	Curb sweeping required from the construction exit and East to the inlet on 57 th street. Remove built up sediment from inlet and maintain inlet BMP.	10/30/18		11/13/18
11	Sweep sidewalk at 57 th and Esperanza, sediment escaping under wattle to sidewalk/gutter.	10/30/18	-	11/13/18
12	Weighted wattle at fence base on Esperanza removed for clean up, assumed replaced at the end of day.	11/13/18		11/13/18
13	NOI should be posted at construction entrance, where the public can see the information. Inspector can provide ASAP. Cumulative storm events for 10/30-31/18 = 0.21"	11/13/18		11/27/18
14	No additional site BMP corrective actions noted at the time of inspection. ECP updated, NOI posted at entrance.	11/27/18		11/27/18

Ver. 070813

Project:

Gorman Contractors for Generations West.

Corrective Action Log

Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09".	12/11/18		12/11/18
No additional site BMP corrective actions noted at the time of inspection. Precipitation			12/26/18
Fractured rock trackout pad required at construction entrance on 58 th street. Curb sweeping required. Tie in work on 57 th .	01/08/19		01/22/19
Replace wattles at fence base on 57 th street and Esperanza. Sweep sidewalk when complete.	01/22/19	Weighted wattle in place, moved when required for tie-in work.	02/05/19
Storm events: 01/10/19=0.18"; 01/11/19=0.12"; 01/13/19= 0.11" ;01/18/19=0.07"	01/22/19		01/22/19
No additional site BMP corrective actions noted at the time of inspection. "Weighted" wattle at fence base on 57th street and Esperanza. Removed and replaced around tie-in work. Continue to monitor replacement of wattle and sweeping of sidewalk if necessary.	02/05/19		02/05/19
No site BMP corrective actions noted at the time of inspection. Storm events: 02/14/19=0.15", 02/19/19= Trace.	02/20/19		02/20/19
No site BMP corrective actions noted at the time of inspection. Storm events: 02/22/19=0.07", 02/23/19=0.01"/ trace, per Weather Underground: Yucca Flats NM KNMALBUQ712	03/07/19		03/07/19
	No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09". No additional site BMP corrective actions noted at the time of inspection. Precipitation event on 12/26/18 recorded at 0.23". Fractured rock trackout pad required at construction entrance on 58th street. Curb sweeping required. Tie in work on 57th. Replace wattles at fence base on 57th street and Esperanza. Sweep sidewalk when complete. Storm events: 01/10/19=0.18"; 01/11/19=0.12"; 01/13/19=0.11"; 01/18/19=0.07" No additional site BMP corrective actions noted at the time of inspection. "Weighted" wattle at fence base on 57th street and Esperanza. Removed and replaced around tie-in work. Continue to monitor replacement of wattle and sweeping of sidewalk if necessary. No site BMP corrective actions noted at the time of inspection. Storm events: 02/14/19=0.15", 02/19/19= Trace. No site BMP corrective actions noted at the time of inspection. Storm events: 02/22/19=0.07", 02/23/19=0.01"/ trace, per Weather Underground: Yucca Flats NM	No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09". No additional site BMP corrective actions noted at the time of inspection. Precipitation event on 12/26/18 recorded at 0.23". Fractured rock trackout pad required at construction entrance on 58 th street. Curb sweeping required. Tie in work on 57 th . Replace wattles at fence base on 57 th street and Esperanza. Sweep sidewalk when complete. Storm events: 01/10/19=0.18"; 01/11/19=0.12"; 01/13/19= 0.11" ;01/18/19=0.07" No additional site BMP corrective actions noted at the time of inspection. "Weighted" wattle at fence base on 57th street and Esperanza. Removed and replaced around tie-in work. Continue to monitor replacement of wattle and sweeping of sidewalk if necessary. No site BMP corrective actions noted at the time of inspection. Storm events: 02/14/19=0.15", 02/19/19= Trace. No site BMP corrective actions noted at the time of inspection. Storm events: 02/22/19=0.07", 02/23/19=0.01"/ trace, per Weather Underground: Yucca Flats NM	No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09". No additional site BMP corrective actions noted at the time of inspection. Precipitation event on 12/26/18 recorded at 0.23". Fractured rock trackout pad required at construction entrance on 58th street. Curb sweeping required. Tie in work on 57th. Replace wattles at fence base on 57th street and Esperanza. Sweep sidewalk when complete. Storm events: 01/10/19=0.18"; 01/11/19=0.12"; 01/13/19= 0.11" (01/18/19=0.07") No additional site BMP corrective actions noted at the time of inspection. "Weighted" wattle in place, moved when required for tie-in work. Storm events: 05/01/19/19=0.11" (01/18/19=0.07") No site BMP corrective actions noted at the time of inspection. Storm events: 02/14/19=0.15", 02/19/19= Trace. No site BMP corrective actions noted at the time of inspection. Storm events: 02/22/19=0.07", 02/23/19=0.01"/ trace, per Weather Underground: Yucca Flats NM

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
)	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?	Yes	No	
10	Are materials that are potential storm water contaminants stored inside or under cover?	Yes	No	
1	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	Yes	No	
2	Has the Site map been updated to reflect current conditions?	Yes	No	The Inspectors map has been updated.
13	Is the NOI posted	Yes	No	NOI Posting Location: Posted at construction entrance.
14	Were previous corrections made within 7 days of last inspection or before the next storm event?	Yes	No	N/A
15	(Other)			
i				
Wa	lk through the facility and look for	signs of pollution	n including paint	, solvents, chemicals, solid waste, oil, and fue
1		lo		
2		Io		

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Print name: Jeff D. Hart	Title: Inspector
Signature: Atlant	Date: <u>03/06/19</u>
SWPPP Management Signature:	Date:

Ver 092314

1	Are the BMPs shown on the map?	Yes	
2	Were there changes to the SWPPP?	No	
3	Has the SWPPP been updated?	No	
4	Were the changes to the SWPPP implemented within 7 days?	Yes	

	New BMPs needed	Notes
1		
2		
3		
4		
5		

Overall Site Issues

A list of corrective actions will be supplied with this inspection.

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	Yes	No	
2	Are natural resource areas (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?	Yes	No	
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	Yes	No	"Weighted" wattle at fence base on 57th street and Esperanza. Removed and replaced around tie-in work. Continue to monitor replacement of wattle and sweeping of sidewalk if necessary.
4	Are discharge points and receiving waters free of any sediment deposits?	Yes	No	
5	Are storm drain inlets properly protected?	Yes	No	
6	Is the construction exit preventing sediment from being tracked into the street?	Yes	No	
7	Is trash/litter from work areas collected and placed in dumpsters?	Yes	No	
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	Yes	No	

Ver 092314 3



2.2.4

Minimize sediment track out

City of Albuquerque Stormwater Construction Site Inspection Report

			General	Information			
Project Na	ime:	Generatio	ns @ West Mes	a			
Location:		5710 Avalo	on Rd NW				
Site Cont	act Name &	Joe Cocchi	na/ Ben Marsh	all ESC File No.	K11E084		
Ag	gency	Gorman Co	ompany Inc.	NPDES Id. No.			
Inspection	Date:	2-15-19	Start/End Time:				
CoA Storn	nwater Inspec	ctor:	10 %		ns, Stormwater Inspector		
Presen	t Phase of			verticle with	some utilities		
Cons	truction:						
Type of Ir	spection:	Regular	Storm Event	Post Storm	Event >0.25" 311/Complaint	x Follow Up	
						58*	
Weath	er at time of i				Temperature: ~	28.	
		Clear					
			since site was P		2 / 4	\neg	
Clarify am	ount: (i.e <1	1/4" to >3/4			5, >3/4"		
				pection			
			Maintenand or Correctiv				
CGP	BMP/	Activity	Action		Location and Notes		
Section			Required				
1.5	Post a	Notice					
	Provide and maintain N	latural buffer when					
2.2.1	Waters of the US <50ft						
2.2.3	Sediment control al	ong any perimeter	х	provide s	provide sediment BMP at 57th St and Esperan		
2.2.3	Sediment control al	ong any perimeter					
2.2.3	Sediment control al	ong any perimeter					
2.2.3	Sediment control al	ong any perimeter	•				
2.2.3	Sediment control al	ong any perimeter	•				
2.2.3	Sediment control al	ong any perimeter	8				
2.2.3	Sediment control al	ong any perimeter					
2.2.3	Sediment control al	ong any perimeter					
2.2.3	Sediment control al	ong any perimeter					
2.2.3	Sediment control al	ong any perimete					
2.2.3 Sediment control along any perimeter							
2.2.3	Sediment control al	ong any perimete					
2.2.3	Sediment control al	ong any perimete	r				
2.2.3	Sediment control al	ong any perimete					
2.2.3	Sediment control al	ong any perimete			2		
2.2.3	Sediment control al	long any perimete	r				
2.2.3	Sediment control al	long any perimete	r				
2.2.4	Minimize sediment	track out	×	clean 57th	St of track out -Central to Nor	th of entrance	

2.2.5	Manage stock piles		
2.2.6	minimize dust		
2.2.10	Protect storm drain inlets		
2.2.10	Protect storm drain inlets		
2.2.11	Minimize erosion of conveyance channels		
2.2.12	Sediment Basins		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.2.14	Stabilize exposed portions of the site		
2.3.1	Equipment and vehicle fueling		
2.3.2	Equipment and vehicle washing		
2.3.3	Building material storage		
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage		
2.3.3	Construction and domestic wastes		
2.3.3	Construction and domestic wastes		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.3.4	Washing applicators used for paint, stucco, concrete, etc.	780	
2.3.4	Washing applicators used for paint, stucco, concrete, etc.		
2.4	Dewatering		
2.1	Discharge off site? (Y/N)	No	
4	Self Inspection Reports		Latest report Date:

Notes: (City Inspector Use) Items in compliance can be left blank.

Maintenance or corrective actions are to be completed within seven (7) days.

Notes:	for the size of this site all BMP installed are functing well. Please provide much sock or
silt fence	(sediment BMP) on east entrance off of 57th St at Esperanza. Track out will require to be
cleaned o	n 57th St from Central to Esperanza.

Timothy

Digitally signed by Timothy E. Sims DN: cn=Timothy E. Sims, o=Stormwater Inspectionos, our=Planning, email=tsims@cabq.gov, c=US Date: 2019.02.15 12:53:39 -07:00'

City of Albuquerque Stormwater Inspector Signature and date: E. Sims

Contact information:

Timothy Sims, 505-803-6155 or

2/15/2019

Construction General Permit (CGP)

Date: 03/06/19

Project:

Gorman Contractors for Generations West.

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
SWPPP Manager	ment Signature:		Date:	

From:

To:

Cc:

Subject: Date: K11E084 - Generations @ West Mesa Friday, February 15, 2019 1:12:36 PM

Attachments:

Joe,

Thanks for meeting with me today, my apologies for the timing; for the size of the site all seems to function well. A few issues noted during my inspection:

- 1. Provide a sediment BMP at the east entrance on 57th St and Esperanza. Some soil may require grading in this area.
- 2. Track out from this area has migrated down Esperanza and to Central on 57th St.— Please clean 57th St to Central and Esperance of sediment.

Thanks,



Stormwater Inspector stormwater quality 505.803.6155

Development & Commercial Stormwater Construction Site Inspection Report

Development & Con	THE CLARK	General Info				
Project Name	Generations	s at West Mes				
Owners/Operators Name	Gorman Ge	Gorman General Contractors, LLC.				
Date of Inspection	01/08/19		Start Time	10:45 am		
Inspector's Name(s)	Jeff D. Har	t				
Inspector's Title(s)	Inspector.					
Inspector's Contact Information		pectionsplusi				
Inspector's Qualifications	Training and SWPPP.	l work experie	nce – see inspecto	r qualification page in section 2 of the		
Type of Inspection: ☐ Regular ☐ During storm e	vent	Post-storm eve	ent			
		Weather Info	ormation			
Has there been a storm event since If yes, provide: Storm Start Date: 12/26/18. App Weather at time of this inspection Clear Cloudy Rain Other: snow/ frozen conditions	roximate Amo		ation (in): 0.25"	☑ Partly Cloudy		
Have any discharges occurred single If yes, describe: What did the water look like at the Are there any discharges at the till If yes, describe: What did the water look like at the	e time of the o	on? No				
 Is a rain gauge installed on site? No Where is it located? Weather Underground (Yucca Flats) and COCORHAS. Has the Rain Event page been filled out? No Inspectors log updated. Are there MSDS sheets on site? Yes Where are they located? Construction trailer. Has the SWPPP been signed on the certification page? No What companies have signed? GormanG.C Have the delegation letters been signed? No What companies have signed? Gorman G.C Has a delegation of authority been filled out for who is signing the inspection reports? No Who is signing the inspection reports? Tom Jones. Has the "Chemical On Site" form been filled out? Yes Construction trailer. Is there a spill kit on site? Yes Where is it located? Construction trailer. Have they done any training for the supervisors or others? Yes Was the inspector able to train any one on this visit? No Who did you speak with? Tom. Are the SWPPP and Yes The SWPPP book and inspections are located at Construction trailer.						
inspections available on site?						
1. 2. 3.		Note	es			

	Final Stabilization/Termination Checklist.							
1.	Are all soil-disturbing activities complete?	No						
2.	Have all inactive areas of the site not covered by pavement or structure achieved a density of 70% coverage?	No						
3.	Date of Final Stabilization.							
	If construction ceases on the site for more t	han 14 days, the site must be sta	ibilized until construction resumes.					
Date	e Construction Stopped	Date Construction Resumed						
Mea the S	sures Taken to Stabilize Site.							

Construction Phasing		
Activity	Current Status	Activity Started / Completed
Installed BMPs	Complete	Started: 08/14/18
		Completed:
Site Clearing and Grading	In progress.	Started: 08/14/18
		Completed:
Installing Utilities	In progress.	Started: 08/28/18
		Completed:
Building Structure	In progress by bldg. letter.	Started: 09/01/18
		Completed:
Paving and Walks		Started:
	9	Completed:
Final Grading/ Stabilize Site		Started:
		Completed:
Other	Utility work in progress on 57 th	Started: 01/08/19

Site-specific BMPs

• The corrective actions initiated and date completed are in the Corrective Action Log.

	List of BMPs Installed	BMP Installed?	BMP Maintenance Required?	Notes
1	Block Wall	Yes	No	
2	Wattles	Yes	No	
3	Portable Toilet	Yes	No	
4	Silt Fence	Yes	No	
5	Stabilized Construction Er	Yes	Yes	See the corrective action log
6	Staging Area	Yes	No	
7	Swale	Yes	No	
8	Cut-back at Curb	Yes	No	
9	Inlet Protection	Yes	No	
10	Concrete Washout	Yes	No	

Ver 092314 2

1	Are the BMPs shown on the map?	Yes	
2	Were there changes to the SWPPP?	No	
3	Has the SWPPP been updated?	No	
4	Were the changes to the SWPPP implemented within 7 days?	Yes	

	New BMPs needed	Notes	
1			
2			
3			
4			
5			

Overall Site IssuesA list of corrective actions will be supplied with this inspection.

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	Yes	No	
2	Are natural resource areas (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?	Yes	No	
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	Yes	No	
4	Are discharge points and receiving waters free of any sediment deposits?	Yes	No	
5	Are storm drain inlets properly protected?	Yes	No	
6	Is the construction exit preventing sediment from being tracked into the street?	Yes	Yes	See the corrective action log
7	Is trash/litter from work areas collected and placed in dumpsters?	Yes	No	
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	Yes	No	

3 Ver 092314

Cherne, Curtis

From: Sent:

Joe Cocchia < jcocchia@gormanusa.com> Wednesday, January 16, 2019 10:15 AM

To:

Cherne, Curtis

Cc: Subject:

Gregg Burke; Bill Cauthen Generations-SWPPP

Attachments:

20190116_100900_resized.jpg

Curtis,

Attached is a picture of another tarp for the dumpster.

Thank you, Joe Cocchia Site Superintendent

CORMAN

P 505-730-4475

E jcocchia@gormanusa.com W https://ddei3-0-

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=www.gormanusa.com&umid=4AF65984-7F96-7405-84C2-E6A3885C3DC8&auth=f0ebcd052f61e7a39dc93191e8a01d02608499af-6da4918e08e1df84b4686170a665026b4722b532









From: Joe Cocchia < jcocchia@gormanusa.com> Sent: Wednesday, January 16, 2019 10:10 AM To: Joe Cocchia < jcocchia@gormanusa.com>

Subject:

Sent from my T-Mobile 4G LTE device

This message has been analyzed by Deep Discovery Email Inspector.

	¥		

	BMP/activity	Implemented	Maintenance Required?	Corrective Action Needed and Notes.
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills leaks, or any other deleterious material?	Yes	No	
10	Are materials that are potential storm water contaminants store inside or under cover?	Yes	No	
11	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	Yes	No	
12	Has the Site map been updated reflect current conditions?	to Yes	No	The Inspectors map has been updated.
13	Is the NOI posted	Yes	No	NOI Posting Location: Posted at construction entrance.
14	Were previous corrections mad within 7 days of last inspection before the next storm event?		No	N/A
15	(Other)	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
			tion including paint	, solvents, chemicals, solid waste, oil, and fu
1	Are there any signs of hazardous materials being exposed to storm water runoff?	No	es Ta	
2	Have there been any reportable quantities	No		

Wa	lk through the facility and	look for signs of	pollution including paint, solvents, chemicals, solid waste, oil, and fuel.
1	Are there any signs of hazardous materials being exposed to storm water runoff?	No	
2	Have there been any reportable quantities releases of hazardous materials?	No	

CERTIFICATION STATEMENT

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief true accurate and complete. Lam aware that there are significant penalties for submitting false information.

Print name: <u>Jeff D. Hart</u>	Title: Inspector
Signature: Hart	Date: <u>01/08/19</u>
SWPPP Management Signature:	Date:

Project:

Gorman Contractors for Generations West.

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
01	BMP's in place prior to earth disturbing activities. No site corrective actions noted at the time of inspection.	08/14/18		08/14/18
02	Maintain inlet at 57 th and Avalon: Clear sediment, repair wattle and coco mat.	08/28/18		09/04/18
03	Post NOI at construction entrance.	08/28/18		09/04/18
04	No additional site BMP corrective actions noted at the time of inspection.	09/04/18		09/04/18
05	No additional site BMP corrective actions noted at the time of inspection. Sediment built up at inlet on 57 street caused by AUI from uphill slope.	09/11/18		09/11/18
06	No additional site BMP corrective actions noted at the time of inspection.	09/18/18		09/18/18
07	Add rock to trackout pad to prevent sediment transfer to street, continue to sweep exit.	09/25/18	1	10/02/18
08	No additional site BMP corrective actions noted at the time of inspection. Active work to remove stockpile from North east corner.	10/02/18		10/02/18
09	Sweep construction exit, sediment transfer to roadway.	10/16/18	10/18/18	10/30/18
10	Curb sweeping required from the construction exit and East to the inlet on 57 th street. Remove built up sediment from inlet and maintain inlet BMP.	10/30/18		11/13/18
11	Sweep sidewalk at 57 th and Esperanza, sediment escaping under wattle to sidewalk/gutter.	10/30/18		11/13/18
12	Weighted wattle at fence base on Esperanza removed for clean up, assumed replaced at the end of day.	11/13/18		11/13/18
13	NOI should be posted at construction entrance, where the public can see the information. Inspector can provide ASAP. Cumulative storm events for 10/30-31/18 = 0.21"	11/13/18		11/27/18
14	No additional site BMP corrective actions noted at the time of inspection. ECP updated, NOI posted at entrance.	11/27/18		11/27/18

Date: 01/08/19

Project:

Gorman Contractors for Generations West.

Corrective Action Log

Corrective Action Needed	Date Action Noted	Date Corrected	Correction Noted By Inspector
No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09".	12/11/18		12/11/18
No additional site BMP corrective actions noted at the time of inspection. Precipitation	12/26/18		12/26/18
Fractured rock trackout pad required at construction entrance on 58 th street. Curb sweeping required. Tie in work on 57 th .	01/08/19		
	No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09". No additional site BMP corrective actions noted at the time of inspection. Precipitation event on 12/26/18 recorded at 0.23". Fractured rock trackout pad required at construction entrance on 58 th street. Curb	No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09". No additional site BMP corrective actions noted at the time of inspection. Precipitation event on 12/26/18 recorded at 0.23". Fractured rock trackout pad required at construction entrance on 58 th street. Curb	No additional site BMP corrective actions noted at the time of inspection. Rain event on 12/02/18 recorded at 0.09". No additional site BMP corrective actions noted at the time of inspection. Precipitation event on 12/26/18 recorded at 0.23". Fractured rock trackout pad required at construction entrance on 58 th street. Curb

Date:

SWPPP Management Signature:

Cherne, Curtis

From: Sent:

Joe Cocchia < jcocchia@gormanusa.com> Wednesday, January 16, 2019 8:52 AM

To:

Cherne, Curtis

Cc: Subject: Gregg Burke; Bill Cauthen RE: Generations-SWPPP

Mornin' Curtis,

I will get you a pic of the new tarp, the first one went quick.

We are not self-performing the SWPPP audits although I will get you the latest from Inspections plus.

Thank you,

Joe Cocchia

Site Superintendent

CORMAN

P 505-730-4475

E jcocchia@gormanusa.com W https://ddei3-0-

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=www.gormanusa.com&umid=97020397-7F95-5905-BEB1-170861FF230F&auth=f0ebcd052f61e7a39dc93191e8a01d02608499aff2b14bd21752ad35019086930f915d9d1aff52eb







From: Cherne, Curtis < CCherne@cabq.gov > Sent: Wednesday, January 16, 2019 8:23 AM To: Joe Cocchia < jcocchia@gormanusa.com >

Subject: RE: Generations-SWPPP

Joe,

Good morning. Lookin' good.

Please send pic of tarp when you get it and I still need your latest SWPPP self-inspection report.



CURTIS CHERNE, PE, QCIS

principal engineer stormwater quality o 505.924.3420

e ccherne@cabq.gov

cabq.gov/planning

From: Joe Cocchia [mailto:jcocchia@gormanusa.com]

Sent: Friday, January 11, 2019 8:16 AM

To: Cherne, Curtis

Cc: Bill Cauthen; Gregg Burke Subject: Generations-SWPPP

Good morning Curtis,

As you can see from the attached pictures, we have a spill kit on site, we have the NOI posted on the entrance gate, we have unburied the waddle on the East side and cleaned it up, I do still owe a tarp for covering the dumpster which I will have in hand today.

Thank you, Joe Cocchia Site Superintendent

CORMAN

P 505-730-4475

E jcocchia@gormanusa.com W https://ddei3-0-

ctp.trendmicro.com:443/wis/clicktime/v1/query?url=www.gormanusa.com&umid=DBE92EC0-7F30-5405-BAE9-5709C5573BBB&auth=f0ebcd052f61e7a39dc93191e8a01d02608499afa188513fc2b429f99388966794804e517c047f6c









From: Joe Cocchia < jcocchia@gormanusa.com>

Sent: Friday, January 11, 2019 8:06 AM To: Joe Cocchia < jcocchia@gormanusa.com>

Subject:

Sent from my T-Mobile 4G LTE device

This message has been analyzed by Deep Discovery Email Inspector.

-----This message has been analyzed by Deep Discovery Email Inspector.

Cherne, Curtis

From: Joe Cocchia <jcocchia@gormanusa.com>
Sent: Wednesday, January 09, 2019 2:21 PM

To: Cherne, Curtis

Subject: Re: Generations at West Mesa Construction Site Inspection

Attachments: image001.jpg

We are cleaning the driveway now also taking care of digging out the waddle along the east fence as we type. I will send you pictures when complete.

Thanks Curtis.

Joe

Sent from my T-Mobile 4G LTE device

----- Original message------From: Cherne, Curtis

Date: Wed, Jan 9, 2019 2:16 PM

To: Joe Cocchia;

Cc:

Subject: Generations at West Mesa Construction Site Inspection

Joe,

Good afternoon.

Thanks for taking the time to walk the site with me today.

As discussed on-site, the following issues were observed at today's inspection:

- 1. The dirt is too high along the east side; it is over the mulch sock. Please mitigate.
- 2. The NOI posting on the trailer may be visible from the street, but it would be better closer to the road so someone can read it without entering the site.
- 3. No spill kit onsite.
- 4. Please get a tarp for the dumpster.
- 5. Sediment in street by the track-out pad. Please remove.

Please send me the latest SWPPP inspection report.

Standard mitigation time is seven days.

As discussed, if you prefer, you can send me pics of the mitigated items. This saves me the trip and saves the owner the \$100 inspection fee. Your e-mail will bounce if the message with pics is greater than 10 Mbyte. It won't tell you it bounced.

Thanks,
[one ABQ]

CURTIS CHERNE, PE, QCIS
principal engineer
stormwater quality
o 505.924.3420
e ccherne@cabq.gov<mailto:ccherne@cabq.gov>
cabq.gov/planning

This message has been analyzed by Deep Discovery Email Inspector.