

City of Albuquerque Stormwater Construction Site Inspection Report

			General	Information				
Project Nar	ne:	Zocalo Lofts						
Location:		4th St and Co	4th St and Coal Loe Sena ESC File No. K14E112					
Site Contact Name &		Joe Sena				K14E112		
Agency		Insight Const	Insight Construction			NMR1001BC		
Inspection Date:		05/23/19	itart/End Time:	9:05	9:20			
CoA Storm	water Inspec	tor:	Curtis Cherne					
	tion Phase:		electrical work, bldg exterior complete Regular Storm Event Post Storm Event > 0.25" 311/Complaint Follow Up					
Type of Inspection: X		K Regular	Regular Storm Event		Post Storm Event >0.25" 311/Complaint			
Weath	er at time o	finspection?	Clear/	Windy	Tempe	rature: ~	65	
Estimated	date of last	storm 0.25" c	r greater		5/10/2019			
Item	PHIEN NA							
	The state of	Deficiency/ Corrective Action						
Number							ottogo .	
1	numerous w	ash-outs on the	site.					
	_					-		
								
			***************************************				·	
			*******	-				
					-			
					_			
			·					
					-		_ .	
	_							
					-		***	
		<u>. </u>	· · · · ·					
2.1	Discharge off site	? (Y/N)	No			· · · · · · · · · · · · · · · · · · ·		
				1 - 1 - 1 - 1		2/20/2	010	
4	Self Insp	ection Reports	requested	Latest re	eport Date:	3/26/2	019	
			Marie Land	1/-3/10				
Notes:								
	emove was	h-outs and ser	nd me pics of th	e mitigation				
				C IIII Gation				
Site was o	lean other	than the wash	-outs					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

05/23/19 Centra Chem