

General Permit SWPPP Inspection					
Site Name:	Site Name: Highlands Master SWPPP Inspector: Jeff Hart				
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-we	eekly -	
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event 	Last Precipitation	48h Forecast 70% Chance of Rain	

#### **Inspection Form Instructions**

Review each question for this inspection carefully, then answer YES, NO, or N/A (not applicable). If any of the items below are out of compliance, press the "Add Action Item" button above to add a corrective action.

General Information	
Inspector's Qualifications Trained and work experience - see inspector qualification page in section 2 of the SW	PPP.
Type of Inspection:	<b>Regular</b> During storm event
	Post-storm event
Weather Information	
<u>Last Storm Event Information</u> For information on the last storm event, see the weather event information at the en	d of this inspection.
Weather at time of this inspection?	Clear Cloudy <b>Rain</b>
	Sleet Snowing High Winds
	Partly Cloudy
Have any discharges occurred since the last inspection?	Yes No
If yes, what did the water look like at the time of the discharge?	Clear Partly turbid Very turbid
Are there any discharges at the time of this inspection?	Yes No
If yes, what did the water look like at the time of the discharge?	Clear Partly turbid Very turbid
Is a rain gauge installed on site?	Yes No
If yes, where is it located?	Monitoring nearby gauge, NOAA satellite mapping, Cocorhas and Weather Underground for storm events.

		PECTIONS S			
General Permit SWPPP Inspection					
Site Name:	<u>Highlands Master SWPPP</u> 1218 Copper Ave NE, Albuquerque, NM 87106	Inspector:	Jeff Hart		
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-weekly -		
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event	Last Precipitation 48h Forecast 70% Chance of Rain		
Has the Rain Event	Page been filled out?	Yes	No		
Are there SDS shee	ets on site?	Yes	No		
lf yes, where are th	ey located?		er events accompany the end of eport. No active work on site/ no		
If construction construction res	eases on the site for more than ´ umes.	l4 days, the site must	be stabilized until		
Date Construction	Stopped	01/21	]		
Date Construction	Resumed				
Measures Taken to	Stabilize the Site:	Fabric	ned ground, Wire back silt fence/ fence attached to security fence, ad access.		
Construction Pha	asing				
<u>Verify what stage of </u>	construction the project is in, and record	d dates when activities sta	rted and were completed.		
Installed BMPs		Compl	eted		
Started:		01/21			
Completed:		01/21- stabiliz	lots updated after partial zation.		
Site Clearing and G	rading	Compl	eted		
Started:		06/20-	Phase 1 staging		
Completed:					

06/20- Phase 1



#### **General Permit SWPPP Inspection** Highlands Master SWPPP Site Name: Inspector: Jeff Hart 1218 Copper Ave NE, Albuquerque, NM 87106 Permit #: NMR1003OP K15E034 **Inspection Frequency:** Bi-weekly -Last Rain Event Last Precipitation 48h Forecast Date of Visit: Jun 29, 2021, 9:00:31 AM 70% Chance of Rain ------

Installing Utilities

Started:	
Completed:	
Building Structure	
Started:	
Completed:	
Paving and Walks	
Started:	
Completed:	
Final Grading/Stabilize Site	
Started:	
Completed:	
Other	Started
Started:	Temp. stabilization 01/21

## Site-specific BMPs

The corrective actions initiated and date completed are in the Corrective Action Log

List of BMPs Installed:

Hardened ground, Wire back silt fence/ Fabric fence attached to security fence, Rock pad access.

Are all of the above controls installed?

Do any of the above controls need maintenance?

Yes

No

	General Permit SV	<b>WPPP Inspection</b>	
Site Name:	<u>Highlands Master SWPPP</u> <u>1218 Copper Ave NE, Albuquerque, NM 87106</u>	Inspector:	Jeff Hart
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-weekly -
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event 	Last Precipitation 48h Forecast 70% Chance of Rai
2	ontrols have not been installed or require please list the control and explain.	6" per sweep	ice repairs required on tracts "2 & COA ESC file K15E034 Sidewalk ing required on tracts "2 & 6" per SC file K15E034
Are the BMPs	shown on the map?	Yes	No
Were there an	y changes to the SWPPP?	Yes	No
Has the SWPP	P been updated?	Yes	No
Were the char	nges to the SWPPP implemented within 7 da	ys? Yes	No
List any new B	MPs needed:		new BMPs. Site BMPs are lled for maintenance 06/29/21.
		L	

A list of corrective actions will be su	upplied with this inspection.
---	-------------------------------

### **<u>1. Are all slopes and disturbed areas not actively being worked properly stabilized?</u>**

Implemented?	Yes	No	N/A
Maintenance Required?	Yes	No	N/A
2. Are natural resources (e.g., streams, Arroyos, mature trees, etc.) prot	tected with barr	iers or	similar BMPs?
Implemented?			_

	Yes	No	N/A	
Maintenance Required?	Yes	No	N/A	

3. Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?

		PECTIONS S				
General Permit SWPPP Inspection						
Site Name:	<u>Highlands Master SWPPP</u> <u>1218 Copper Ave NE, Albuquerque, NM 87106</u>	Inspector:	Jeff Hart			
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-weekly -			
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event	Last Precipitation 48h Forecast 70% Chance of Rain			
Implemented?		Yes	No N/A			
Maintenance F	Required?	Yes	No N/A			
<u>4. Are discharge</u>	points and receiving waters free of any sedir	<u>nent deposits?</u>				
Implemented?		Yes	No N/A			
Maintenance F	Required?	Yes	No N/A			
<u>5. Are storm dra</u>	in inlets properly protected?					
Implemented?		Yes	No N/A			
Maintenance F	Required?	Yes	No N/A			
<u>6. Is the constru</u>	iction exit preventing sediment from being tra	acked into the street?				
Implemented?		Yes	No N/A			
Maintenance F		Yes	No N/A			
7. ls trash/litter	from work areas collected and placed in dum	<u>ipsters?</u>				
Implemented?		Yes	No N/A			
Maintenance F		Yes	No N/A			
8. Are washout	<u>facilities (e.g., paint, stucco, concrete) availab</u>	<u>le, clearly marked, and ma</u>	aintained?			
Implemented?		Yes	No N/A			
Maintenance F	Required?	Yes	No N/A			

9. Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?

		PECTIONS S			
General Permit SWPPP Inspection					
Site Name:	<u>Highlands Master SWPPP</u> <u>1218 Copper Ave NE, Albuquerque, NM 87106</u>	Inspector:	Jeff Hart		
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-weekly -		
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event 	Last Precipitation 48h Forecast 70% Chance of Rain		
Implemented?		Yes	No N/A		
Maintenance F	Required	Yes	No N/A		
<u>10. Are material</u>	<u>ls that are potential storm water contaminan</u>	<u>ts stored inside or under c</u>	over?		
Implemented?		Yes	No N/A		
Maintenance F	Required?	Yes	No N/A		
<u>11. Are non-stor</u>	<u>m water discharges (e.g., wash water, dewate</u>	ering) properly controlled?			
Implemented?		Yes	No N/A		
Maintenance F	Required?	Yes	No N/A		
<u>12. Has the Site</u>	map been updated to reflect current condition	ons?			
Implemented?		Yes	No N/A		
Maintenance F	Required?	Yes	No N/A		
<u>13. Is the NOI po</u>	osted?				
Implemented?		Yes	No N/A		
Maintenance F	Required?	Yes	No N/A		
<u>14. Were previo</u>	<u>us corrections made within 7 days of last insp</u>	ection or before the next s	storm event?		
Implemented?		Yes	No N/A		
Maintenance F	Required?	Yes	No N/A		

Walk through facility and look for signs of pollution including paint, solvents, chemicals, solid waste, oil, and fuel.

	General Permit	SWPPP Inspection			
Site Name:	<u>Highlands Master SWPPP</u> 1218 Copper Ave NE, Albuquerque, NM 87106	Inspector:	Jeff	Hart	
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-we	eekly -	
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event 	Last Precipitation	48h Forecast 70% Chance of Rair	
Are there any si vater runoff?	re there any signs of hazardous materials being exposed to storm				

Have there been any reportable quantities releases of hazardous materials?

Additional Notes

Site BMPs are scheduled for maintenance 06/29/21 by Inspections Plus.

## Certification & Signatures

#### Certification Statement:

 $\hat{a} \in \mathbb{C}$  certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. $\hat{a} \in \mathbb{D}$ 

Electronic Signature

X Jeff Hart

Date June 29, 2021 at 10:13:09 AM MDT

Yes

Title Operations Manager



General Permit SWPPP Inspection					
Site Name:	<u>Highlands Master SWPPP</u> <u>1218 Copper Ave NE, Albuquerque, NM 87106</u>	Inspector:	Jeff	Hart	
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-weekly -		
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event 	Last Precipitation	48h Forecast 70% Chance of Rain	

Photos





General Permit SWPPP Inspection							
Site Name:	<u>Highlands Master SWPPP</u> <u>1218 Copper Ave NE, Albuquerque, NM 87106</u>	Inspector:	Jeff Hart				
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-weekly -				
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event 	Last Precipitation	48h Forecast 70% Chance of Rain			

# Weather History



March

All precipitation totals are obtained from the National Oceanic and Atmospheric Administration (NOAA). Precipitation readings are based on the latitude and longitude for each site as entered into complianceGO. Occasionally NOAA fails to return/record data. Days where this occurs are so indicated.



General Permit SWPPP Inspection							
Site Name:	<u>Highlands Master SWPPP</u> <u>1218 Copper Ave NE, Albuquerque, NM 87106</u>	Inspector:	Jeff Hart				
Permit #:	NMR1003OP K15E034	Inspection Frequency:	Bi-weekly -				
Date of Visit:	Jun 29, 2021, 9:00:31 AM	Last Rain Event 	Last Precipitation	48h Forecast 70% Chance of Rain			

There Are No Action Items