

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Na	mo:							
Project Name: Location:		Springhill Suites 1101 Central						
Site Contact Name &		Jeff Harper		ESC File No. K15E034B				
		jeff.harper@jaynescorp.cor				NMR1001RP		
Agency Inspection Date:		06/17/20 Start/End Time: 1030/1050hrs						
CoA Stormwater Inspecto		r· 1	imothy E. Sims	50/1050113				
	ction Phase:	vertical with site work						
Type of Inspection: x					Event >0.25" 311/Complaint Follow Up			
.,peer.	X	Regular				origination of the second seco	I ONOW OP	
Weath	er at time of i	nspection?	Clea	ar	Tempe	rature: ~	82*	
Estimated	date of last s	torm 0.25" or greater			11/27/2019			
Item	Deficiency/ Corrective Action							
Number								
	no issues observed with this inspection							
	***Diasco provide latest SW/DDD solf inspection report							
	***Please provide latest SWPPP self-inspection report.							
	Thanks for staying on top of concrete washouts.							
2.1	Discharge off site?	(Y/N)	No					
4	<u> </u>	tion Reports	requested	Latest rep	ort Date:	3/27/20	020	
L	••					. ,		

Notes:

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155