

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	Springhill Su	ites				
Location:		1101 Central					
Site Contact Name & Agency Inspection Date:		Jeff Harper		ESC File No.		K15E034B	
		ieff harner	@jaynescorp.co	n NPDES Id. No.		NMR1001RP	
		08/12/20	Start/End Time: 0	945/1000hrs		14141142002141	
			Timothy E. Sims	343/10001113			
CoA Stormwater Inspector: Timothy E. Sims Construction Phase: vertical with site work							
	. 1	Desules	Charma Franch		Event >0.25"	211 /Campalaint	I call and the
туре от п	spection: x	Regular	Storm Event	Post Storing	Event >0.23	311/Complaint	Follow Up
\\/aa+la	wat time a of i		Cla		Танана	watuwa. ~	00*
weathe	er at time of i	nspection?	Cle	ear	Tempe	rature: ~	80*
Estimated	date of last s	torm 0.25"	or greater			7/25/2020	
Item			- 6				
	Deficiency/ Corrective Action						
Number							
	no issues observed with this inspection						
	***Dlesse provide latest CM/DDD self inspection report						
	***Please provide latest SWPPP self-inspection report.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	tion Reports		Latest rep	oort Date:	3/27/20	020
Notes:	inspection co	nducted un	der Covid-19 co	nstraints			
				,			
							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

08/12/20____