

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nar	ne:	De Anza					
Location:		4301 Central	NE				
Site Contact Name &		larry Higbee		ESC File No.		K17E106	
Agency		HB Construct	ion	NPDES Id. No.			
Inspection Date:				30/1014)			
CoA Stormwater Inspector: Curtis Cherne							
Construction Phase: vertical							
Type of Ir		Regular	Storm Event		Event >0.25"	311/Complaint X	Follow Up
		- Togular				10 22/ 0011/5101110/71	
Weathe	r at time of i	nspection?	Cle	ar	Tempe	rature: ~	85
Weather at time of inspection? Clear Temperature: ~ 85 Estimated date of last storm 0.25" or greater //30/2019							
Item	Deficiency/ Corrective Action						
Number							
1	no issues observed						
	THE COURSE SWEETING						
					W. (19)		
			1 411		3.00.00.00.00.00.00.00.00.00.00.00.00.00		
			TO MAKE				
			Jacob II				
					212127 1747		
	-						
		-					
	Discharge off site?	(Y/N)	No				
	Self Inspect	ion Reports		Latest re	port Date:		
					p		
10/2							
Notes:							2
		N 20					
7.00							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

07/30/19\_\_\_\_