

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Nan	ne:	Holiday Inn Expi	ress				
Location:		10501 Copper Ave NE					
Site Contact Name &		Owen Johnson, Premier Hospita ESC File I			K21E009H3		
Agency		Johnson.oi@gmail.com NPDES Id. I			NMR1001FF		
Inspection Date:			t/End Time: 10	:00/10:15AM	3.7 1/4 1/6		
CoA Stormy	vater Inspecto	r: Doi	ug Hughes				
Construc	tion Phase:			Site Utilities St			
Type of In	spection:	Regular	Storm Event	Post Storm Ev	vent >0.25" 3	11/Complaint	Follow Up
					SALES SALAN ASSESSMENT		
Weathe	er at time of i	inspection?			Temperat	ure:_~	
Estimated	date of last s	torm 0.25" or greater				7/7/2019	
Item	em l						
	Deficiency/ Corrective Action						
Number							
	Previous issues had been mitigated						
	One new Washout Yellow Point North of Building Resping Styrofour South Spor						
	Deal Class Could some town						
	Nasping Ityrotoum South dolor						
	1/	,					
					1.000		
						- 14480	
	2.000	-0.0					
	200						
			1 04 DE 12 19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
2.1	Discharge off site?	(Y/N)	No				
			IVU			0/0/00	
4	Self Inspec	tion Reports		Latest repo	ort Date:	8/9/20:	L9
TO THE STATE OF							
Notes:							
		-				- 24.7	
	2 - 1 - 1 - Wa			7,555.00		240	
-				-		_	
						1477	
						3000	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Doug Hughes (505) 924-3420

jhughes@cabq.gov

Doug Bufle 8/23/2019