

City of Albuquerque Stormwater Construction Site Inspection Report

| General Information | | | | | | | |
|---|-------------------------------|-----------------------|---------------|---------------|-----------|------------|------|
| Project Name: | | Maverik | | | | | |
| Location: | | 650 Juan Tabo | | | | | |
| Site Contact Name & | | Jason - Insight Const | | ESC File No. | | K22E059 | |
| Agency | | jason@insisg | | NPDES Id. No. | NMR10022L | | |
| Inspection Date: | | | | 300/1315hrs | | | |
| | vater Inspectoi | r: Tiı | mothy E. Sims | | | | |
| Construction Phase: vertical | | | | | | | |
| Type of Inspection: x Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up | | | | | | | |
| | | | | | | | |
| Weathe | er at time of i | nspection? | Cle | ar | Tempe | rature: ~ | 55* |
| Estimated | date of last s | torm 0.25" or | greater | | | 11/27/2019 | |
| Item | Deficiency/Compating Astism | | | | | | |
| Number | Deficiency/ Corrective Action | | | | | | |
| Nullibei | no issues observed | | | | | | |
| | 110 133003 0030 | iveu | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | _ | - | | | |
| 2.1 | Discharge off site? | (Y/N) | No | | | | |
| 4 | Self Inspect | ion Reports | | Latest rep | ort Date: | 1/15/ | 2020 |
| | | | | | | | |
| | | | | | | | |
| Notes: This project requires SWPPP self-inspection reporting until the work order is complete | | | | | | | |
| on Juan Tabo. | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

02/27/20_____