

City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	nformation				
Project Nar	ne:	Maverik						
Location:		650 Juan Tabo)					
Site Contact Name & Agency		Jason - Insight	Const	ESC File No.	K22E059			
		jason@insisg		NPDES Id. No.		NMR10022L		
Inspection Date:		10/17/19 St	art/End Time: 08	300/0820hrs				
	water Inspector	r: Ti	mothy E. Sims					
Construction Phase: vertical								
Type of Inspection: x Regular Storm Event Post Storm Event >0.25" 311/Complaint x Follow Up								
Weather at time of inspection? Clear Temperature: ~ 55*								
Weath	er at time of i	nspection?	Clea	ar	Tempe	Temperature: ~ 55*		
Estimated	date of last storm 0.25" or greater 10/4/2019							
Item	Deficiency/ Corrective Action							
Number	Deficiency/ Corrective Action							
	Mitigate all washouts on site. North of refuse his south of building and at Superintendent's							
1	Mitigate all washouts on site. North of refuse bin, south of building, and at Superintendent's							
	trailer. Ensure trades utilize provided washout facility. This facility may need to be relocated							
	closer to work site or provide a secondary location.							
2	Trackout on Zia, from entrance to Paisano requires removal. A follow up inspection will occur							
	tomorrow. (Trackout is required to be removed daily.)							
			•	,				
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspect	ion Reports		Latest rep	ort Date:	10/7/	/2019	
Notes:								

 ${\bf City\ of\ Albuquerque\ Stormwater\ Inspector\ Signature\ and\ date:}$

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

10/17/19____