Development & Commercial Stormwater Construction Site Inspection Report

General Information						
Project Name	Maverick Gas Station on Juan Tabo					
Owners/Operators Name	Insight Construction					
Date of Inspection01/15/20Start Time10:15 AM						
Inspector's Name(s)	Marcos Valadez					
Inspector's Title(s) Inspector						
Inspector's Contact Information	marcos@inspections					
Inspector's Qualifications	Training and work exp SWPPP.	erience – see inspector	qualification page in section 2 of the			
Type of Inspection: ☐ Regular ☐ During storm events and a comparison of the compar	vent Post-storm	event				
		Information				
Has there been a storm event since		No				
If yes, provide:	The mot mapped and					
Storm Start Date: Approxi	imate Amount of Precip	tation (in):				
Weather at time of this inspection? ☐ Clear ☐ Cloudy ☐ Rain ☐ Other:	Sleet Snow	ing High Winds	☐ Partly Cloudy			
Have any discharges occurred since If yes, describe: What did the water look like at the Are there any discharges at the tin	e time of the discharge	No Clear Partly tui	bid Very turbid			
If yes, describe: What did the water look like at the	-	Clear 🗌 Partly tui	bid Very turbid			
 Is a rain gage installed on site? Yes Where is it located? on top of the conex box Has the Rain Event page been filled out? No Are there MSDS sheets on site? Yes Where are they located? construction trailer Has the SWPPP been signed on the certification page? Yes What companies have signed? Insight Construction Have the delegation letters been signed? Yes What companies have signed? Insight Construction 						
6. Has a delegation of author the inspection reports? Jo			ection reports? Yes Who is signing			
7. Has the "Chemical On Sit						
8. Is there a spill kit on site?	Yes Where is it loca	ted? Construction trai	er			
9. Have they done any training for the supervisors or others? Yes10. Was the inspector able to train any one on this visit? Yes Who did you speak with? Joseph - Site Superintendent						
Are the SWPPP and inspections available on site? Yes The SWPPP book and inspections are located at The construction trailer.						
Notes						
1. Send inspections to - Jason Bianchetti - jason@insightnm.com 2.						
3						

	Final Stabilization/Termination Checklist.					
1.	Are all soil-disturbing activities complete?	Yes				
2.	Have all inactive areas of the site not covered by pavement or structure achieved a density of 70% coverage?	Yes				
3.	Date of Final Stabilization.	Yes	01/15/20 Stabilized with concrete, paving and gravel			
	If construction ceases on the site for more	than 14 days, the sit	e must be stabilized until construction resumes.			
Dat	Date Construction Stopped Date Construction Resumed					
1	asures Taken to Stabilize Site.					

Construction Phasing		
Activity	Current Status	Activity Started / Completed
Installed BMPs	Silt fence, Mulch sock, Inlet protection, Portable Toilet	Started:
		Completed: 07/10/19
Site Clearing and Grading		Started:
		Completed:
Installing Utilities	Completed	Started: 07/17/19
		Completed: 01/15/20
Building Structure	Completed	Started: 08/28/19
		Completed: 01/15/20
Paving and Walks	Completed	Started: 01/02/20
		Completed: 01/15/20
Final Grading/ Stabilize Site	Final Stabilization	Started:
		Completed: 01/15/20
Other		Started:
		Completed:

Site-specific BMPs

• The corrective actions initiated and date completed are in the Corrective Action Log.

	List of BMPs Installed	BMP Installed?	BMP Maintenance Required?	Notes
1	Inlet Protection	Yes	Yes	See the corrective action log
2	Silt Fence	Yes	No	
3	Mulch Socks	Yes	No	
4	Portable Toilet	Yes	No	
5	Concrete Washout	Yes	No	
6	Stabilized Construction	Yes	No	
	Entrance			
7	Roll off	Yes	No	
8				
9				
10				

1	Are the BMPs shown on	Yes
	the map?	
2	Were there changes to	No
	the SWPPP?	
3	Has the SWPPP been	No
	updated?	
4	Were the changes to the	
	SWPPP implemented	
	within 7 days?	

	New BMPs needed	Notes
1		
2		
3		
4		
5		

Overall Site Issues

A list of corrective actions will be supplied with this inspection.

	BMP/activity	Implemented?	Maintenance Required?	Corrective Action Needed and Notes.
1	Are all slopes and disturbed areas not actively being worked properly stabilized?	Yes	No	
2	Are natural resource areas (e.g., streams, Arroyos, mature trees, etc.) protected with barriers or similar BMPs?	Yes	No	
3	Are perimeter controls and sediment barriers adequately installed (keyed into substrate) and maintained?	Yes	No	
4	Are discharge points and receiving waters free of any sediment deposits?	Yes	No	
5	Are storm drain inlets properly protected?	Yes	Yes	See the corrective action log
6	Is the construction exit preventing sediment from being tracked into the street?	Yes	No	
7	Is trash/litter from work areas collected and placed in dumpsters?	Yes	No	
8	Are washout facilities (e.g., paint, stucco, concrete) available, clearly marked, and maintained?	Yes	No	Use the concrete washout for any type concrete.

	BMP/activity	Imple	mented?	Maintenance Required?	Corrective Action Needed and Notes.	
9	Are vehicle and equipment fueling, cleaning, and maintenance areas free of spills, leaks, or any other deleterious material?		No	No		
10	Are materials that are potential storm water contaminants stored inside or under cover?		/es	No		
11	Are non-storm water discharges (e.g., wash water, dewatering) properly controlled?	1	No	No		
12	Has the Site map been updated reflect current conditions?	to Y	Z'es	No	The Inspectors map has been updated.	
13	Is the NOI posted	Y	/es	No	NOI Posting Location: At the entrance of the site (Copper Ave).	
14	Were previous corrections made within 7 days of last inspection or before the next storm event?		/es	No		
15	(Other)					
Wa	lk through the facility and look	for signs of	pollution	including paint.	solvents, chemicals, solid waste, oil, and fuel.	
1	Are there any signs of hazardous materials being exposed to storm water runoff?	No				
2	Have there been any reportable quantities releases of hazardous materials?	No				
		CE	RTIFICA	TION STATEM	ENT	
	"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."					
	D				Title. In such	

Print name: Marcos Valadez Title: Inspector

Date: 01/15/20

Project:

Maverick Gas Station on Juan Tabo

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
1	Install a rain gauge	07/10/19		07/26/19
2	Ensure there is a spill kit	07/10/19		07/24/19
3	Remove the blow away trash around the site perimeter	07/17/19		07/24/19
4	Install a rock pad entrance to reduce tracking of sediment onto streets.	07/17/19		07/24/19
5	Sweep on Copper Ave. and Zia Rd. for off site tracking	07/24/19		07/31/19
6	Install Mulch sock at the Northwest corner and Southeast corner of the site. Approx. 150' to prevent sediment runoff going down the street.	07/31/19		08/07/19
7	Have an authorized representative from Insight Construction Sign the Certification and Delegation Letter in the SWPPP Book	07/31/19		08/21/19
8	No new issues at the time of this inspection	08/07/19		08/07/19
9	The site looked good . No new issues at the time of this inspection	08/14/19		08/14/19
10	No new issues at the time of this inspection	08/21/19		08/21/19
11	No new issues at the time of this inspection	08/28/19		08/28/19
12	The site looked good . No new issues at the time of this inspection	09/04/19		09/04/19
13	Remove the dirt against the security fence along Zia Road and adjust the mulch sock	09/11/19		12/18/19
14	No new issues at the time of this inspection	09/18/19		09/18/19
15	No new issues at the time of this inspection	09/25/19		09/25/19
16	Sweep at the entrance for off site tracking	10/09/19		12/18/19
17	The trash bin needs to be emptied	10/23/19		11/06/19
18	Repair or replace the silt fencing on Paisano and Zia Road.	10/23/19		11/20/19
19	Clean up the concrete washed out at the corner of Juan Tabo and Copper Ave,	10/23/19		11/06/19
20	Clean up the concrete washed out at the south side of the building.	11/06/19		11/20/19
21	Clean the inlet protection on Copper Ave,	11/06/19		
22	Sweep at the entrance for off site tracking	11/20/19		12/18/19
23	Install Construction Entrance/Track Out Pad. 12/18/19 The site will be paved next week.	12/04/2019		12/18/19
24	Install Stock pile Protection	12/04/2019		01/02/20

Ver. 070813

Date: 01/15/20

Project:

Maverick Gas Station on Juan Tabo

Corrective Action Log

Number	Corrective Action Needed	Date Action Noted	Date Corrected	Date Correction Noted By Inspector
25	No new issues at the time of this inspection	12/18/19		12/18/19
26	No new issues at the time of this inspection	01/02/20		01/02/20
27	The site has been stabilized. Paving has been completed, Remove the inlet protection on Copper Ave.	01/15/20		

SWPPP Management Signature: Date:

Ver. 070813