

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Solare Collegiate Charter School					
Location:		Gibson and Barbados					
Site Contact Name &		Rachel Sewards		ESC File No.	M09E031		
Agency		Solare Collegiate Foundation		NPDES Id. No.		NMR10026S	
Inspection Date:			Start/End Time:	8:45/8:50	returned	9:40/10:00	
CoA Stormwater Inspector: Curtis Cherne grading							
Type of Inspection: X		Regular Storm Event			grading Storm Event >0.25"   311/Complaint		Follow Up
Type of II	ispection. [X	Kegulai	13totili Evelit	11 031 3101111	EVEIN > 0.25	[311/Complaint]	Tronow op
Weathe	er at time of i	nspection?	Cle	ar	Temperature: ~		
Estimated	date of last s	torm 0.25" c			5/10/2019		
Item				Table Tree			
	Deficiency/ Corrective Action						
Number							
1	Site not posted						
2	No vechicle tracking control (track-out) pad						
3	minor track-out across cattle guard drain						
4	Vehicle tracking control in wrong location						
5	dirt ramp constructed in Barbados St.						
6	sediment in gutter on Barbados St. May be related to installation of the silt fence						
7	No inlet protection						
8	silt fence not buried along east edge in multiple locations for a total of approx 120 feet						
9	sediment pile on Gibson Blvd 5 feet uphill from drain. May be related to the installation of the silt fc.						
						<u>"-</u>	
				_			
						··	
					·		
			-				
2.1	Discharge off site?	(Y/N)	No		_		
4	Self Inspec	tion Reports		Latest re	port Date:		
		•			-		
Notes:						·	
silt fence was installed around perimeter of site							
<del></del>	·						<del></del>

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

06/11/19 hut a chu