

City of Albuquerque Stormwater Construction Site Inspection Report

General Information									
Project Nar	ne:	Solar Collegiate Charter School							
Location:		gibson & 98th St							
Site Contact Name &		Daniel Reaces - Insight		ESC File No. M09E031					
Agency		daniel@insightnm.com		NPDES Id. No.	NMR10026S				
Inspection Date:				800/0845hrs					
CoA Storm	water Inspecto								
	ction Phase:	vertical					_		
Type of Ir	spection: x	Regular	Storm Event	Post Storm B	Event >0.25"	311/Complaint	Follow Up		
Weath	or at time of i	nenaction2	Clas	or l	Tompo	raturo: ~	71*		
Weather at time of i Estimated date of last s		torm 0.25"	Clea or greater	di	Tempe	rature: ~ 7/7/2019	/1		
		101111 0.25				77772019			
Item	Deficiency/ Corrective Action								
Number									
	no issues observed with this inspection								
	Please provide latest SWPPP self-inspection report								
2.1	Discharge off site?	(Y/N)	No						
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	8/2/20	19		

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155