



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

Project Name:	Solar Collegiate Charter School				
Location:	gibson & 98th St				
Site Contact Name & Agency	Daniel Reaces - Insight	ESC File No.	M09E031		
	daniel@insightnm.com	NPDES Id. No.	NMR10026S		
Inspection Date:	01/13/20	Start/End Time:	1110/1130hrs		
CoA Stormwater Inspector:	Timothy E. Sims				
Construction Phase:	vertical				
Type of Inspection:	<input checked="" type="checkbox"/> Regular	<input type="checkbox"/> Storm Event	<input type="checkbox"/> Post Storm Event >0.25"	<input type="checkbox"/> 311/Complaint	<input type="checkbox"/> Follow Up

Weather at time of inspection?	Cloudy	Temperature: ~	40*
Estimated date of last storm 0.25" or greater	11/27/2019		

Item Number	Deficiency/ Corrective Action			
	no issues observed with this inspection			
	***Please provide latest SWPPP self-inspection report.			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	requested	Latest report Date:	11/22/2019

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Timothy E. Sims - (505) 803-6155
tsims@cabq.gov 01/13/20