

City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	nformation				
ESC File No. M09E03		, ,		Solare Collegiate Charter School				
NPDES Id. No.	IPDES Id. No. NMR10026S/NMR10026D		Location: Gibson and Barbad		and Barbados			
6/14/2021 Owner					Contractor			
			Collegiate Foundation		Insight			
ooman or man		Rachel Sewards			Daniel reaves			
e-mail		rsewards@solarecollegiate.com			daniel.reaves@insightnm.com			
Contact Phone #		505-917-6442			505-506-9944			
COA Inspector					Start/End Time: 1:30 PM-1:55 PM			
Construction Phase:		Vertical					1	
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up	
Weather at time of in					Temperature: ~ 94			
Estimated	date of last s	torm 0.25"	or greater		5/31/2021			
Item	Deficiency/Corrective Action							
Number	Deficiency/ Corrective Action							
1	Silt fence needs to be installed, replaced, and repaired. Repair/maintain silt fences across entire							
-	perimiter of site.							
	· ·						. :	
2			must be kept on si	te, or it not k	kept on site, th	ie location must be	aentified	
	on the NOI posting.							
3	Sediment in the street/sidewalk. Sweep and remove sediment from the streets/sidewalks daily.						daily.	
4	Areas not stabilized. Areas inactive for more than 14 days must be stabilized per CGP 2.2.14.							
4	Areas not stabilized. Areas inactive for more than 14 days must be stabilized per CGF 2.2.14.							
5	Domestic waste on ground. Pick up waste daily and place in an approved waste container.							
6	Weed accumulation in pond. Remove tumbleweeds per City Ordinance § 9-8-4							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	Requested	Latest re	port Date:	1/3/20	20	

Notes:	Mr. Reaves said that a SWPPP was not kept on site because the site is less than an acre.						

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

Thomas Evans 06/17/2021

tevans@cabq.gov