

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	M09E	1 -			Solare Collegiate Charter School		
NPDES Id. No.	NMR10026S/N	NMR10026D	Location:		Gibson and Barbados		
7/6/2021		Owner			Contractor		
Operator		Solare Collegiate Foundation			Insight		
Contact name & title		Rachel Sewards			Daniel reaves		
e-mail		rsewards@solarecollegiate.com			daniel.reaves@insightnm.com		
Contact Phone #		505-917-6442			505-506-9944		
COA Inspector		Thomas Evans			Start/End Time: 2:35 PM-2:45 PM		
Construction Phase: Vertical							
	nspection:	Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
	er at time of i		clea	ar	Temperature: ~ 94		
Estimated date of last storm 0.25" or greater 7/6/2021							
Item							
Number	Deficiency/ Corrective Action						
	Cilt fance needs to be installed replaced and repaired. Denoir/maintain silt fances corress entire						
1	perimiter of site.						
2	2 SWPPP location not identified on the NOI posting.						
3	Sediment in the street/sidewalk. Sweep and remove sediment from the streets/sidewalks daily.						
							-
4	Areas not stabilized. Areas inactive for more than 14 days must be stabilized per CGP 2.2.14.						
4	Areas not stabilized. Areas mactive for more than 14 days must be stabilized per CGP 2.2.14.						
5	Domestic waste on ground. Pick up waste daily and place in an approved waste container.						
6	Weed accumulation in pond. Remove tumbleweeds per City Ordinance § 9-8-4						
7	Self-inspection reports not received upon last request.						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	tion Report	Requested	Latest re	port Date:	1/3/20	20
				<u> </u>			
Notes:	No changes to perimeter/inactive areas since last inspection on 6/14/2021.						

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans

07/07/2021