



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	M09E031	Project Name:	Solare Collegiate Charter School Phase 3			
NPDES Id. No.	NMR1006UK	Location:	8801 Gibson Blvd SW			
12/5/2024	Owner	Contractor				
Operator	Solare Collegiate Foundation	Insight				
Contact name & title	Rachel Sowards	John Rescate				
e-mail	rsowards@solarecollegiate.org	john.rescate@insightnm.com				
Contact Phone #	505-917-6442	505-888-7927				
COA Inspector	James Hughes	Time	10:20am			
Construction Phase:	grading					
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	
Weather at time of inspection?		Temperature: ~		30		
Estimated date of last storm 0.25" or greater		11/7/2024				
Item Number	Deficiency/ Corrective Action					
1	none - All previous violations mitigated					
2	SWPPP - Rachel Sowards must sign the certification statement on all self-inspection reports, and the signed copy must be available onsite. There wasn't even a place for her to sign on the reports, and her signature was missing from all of them. You and your stormwater team should study Appendix 11.2 of the CGP together and comply with the permit.					
2.1	Discharge off site? (Y/N)	no				
4	Self Inspection Reports	requested	Latest report Date:	1/2/2025		
Notes:						
The SWPPP is in the Conex						

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: James Hughes
jhughes@cabq.gov

1/22/2025

James D. Hughes