

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No. M09E		032   Project Name:			Sombra del Oeste		
NPDES Id. No. NMR10		D5WH Location: Gi		oson Blvd and Valley Cottonwood SW			
7/2	/2024	Owner	•		Contractor	,	
Operator		Homewise Inc.					
Contact name & title		Eugene Chavez					
e-mail		echavez@homewise.org					
Contact Phone #		505-983-9473					
COA Inspector		Chancellor English			Start/End Time: 10:30am		
Construction Phase:					tarted		
Type of Inspection:		Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up
Weather at time of i		nspection?	Clea	ır	Temper	ature: ~	90
	date of last s					6/30/2024	
Item				y/ Correctiv	e Action		
Number							
1	BMPs - The pe	rimeter silt f	ence is both damag	ged and overl	oaded and the	inlet protection	at the
	intersection of Gibson Blvd and Barbados Ave requires repair, both in violation of CGP Part 2.1.4.						
	Required mitigation: Ensure all stormwater controls are maintained and remain in effective operating						
	1 ' - 1						
	condition during permit coverage and are protected from activities that would reduce their						
	effectiveness per CGP Part 2.1.4.						
2.1	Discharge off site?	(Y/N)	no	1			
4	Self Inspect			Latest rer	oort Date:	N/A	
	Jen mapeet	лоп перога	3 110	Latestic	ort Bate.	14/71	
Notes:							

City of Albuquerque Stormwater Inspector Signature and date: 7/3/2024

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

Chancellor English