

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No. M15E008 Project Name:					Wagoner Building			
NPDES Id. No.	NMR1005TB/I	MR1005TC Lo	cation:		1800 Randolph Rd SE			
5/2	28/2025 Owner				Contractor			
Operator		LOE Investments LLC			Eastley Inc.			
Contact name & title		Matt Wagoner			Matt Wagoner			
e-mail		matt@eastleyinc.com			matt@eastleyinc.com			
Contact Phone #		951-712-1394			951-712-1394			
COA Inspector		Chancellor English			Start/End Time: 11:45am			
Construction Phase: Foundations							_	
Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint Follow Up								
Weath	er at time of i	spection? Clear			Temperature: ~ 85			
Estimated	date of last s	torm 0.25" or	rm 0.25" or greater			5/4/2025		
Item	Deficiency/ Corrective Action							
Number	Deficiency corrective Action							
1	Posting - CGP coverage was not posted so it is visible from the public right-of-way in violation of CGP							
	Part 1.5. Required mitigation: You must post a sign or other notice of your permit coverage at a safe,							
	publicly accessible location in close proximity to the construction site per CGP Part 1.5. The notice							
	must be located so it is visible from the public road that is nearest to the active part of the							
	·							
	construction site, and it must use a font large enough to be readily viewed from a public right-of-way.							
2	SWPPP - The SWPPP and self-inspection reports were unavailable at the time of inspection in violation							
_	of CGP Parts 4.7.3 and 7.3. Required mitigation: You must keep a current copy of your SWPPP and a							
	copy of all inspection reports at the site or at an easily accessible location, so that it can be made							
	immediately available at the time of an on-site inspection per CGP Parts 4.7.3 and 7.3. If an on-site							
	location is unavailable to keep the SWPPP and self-inspection reports when no personnel are present,							
	notice of the plan's location must be posted near the main entrance of your construction site.							
2	DAADa. The silk farmer on the month and common has been taken and an add to be made in the silk farmer.							
3	BMPs - The silt fence on the northeast corner has been taken down and needs to be re-installed in							
	violation of CGP Part 2.1.2. Required mitigation: Design and install all stormwater controls in							
	accordance with good engineering practices, including applicable design specifications per CGP Part							
	2.1.2.							
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	ion Reports	No	Latest rer	oort Date:	N/A		
•						,,,		
A. .								
Notes:								

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov

5/29/2025

Chancellor English