ECS File: MISEvi2



City of Albuquerque Stormwater Construction Site Inspection Report

	General Information			
			SVENING SERVICE STREET	
Project Name	Gibson Rising.			
and Location	Gibsun Rising Gibsun au University Josh 5/karsgard Contact Phone #/ Red Shanrock Contact Phone #/ E-mail 262-2323			
	Josh Skarcoard	G	505	
Site Contact Name & Agency	1	Contact Phone #/ E-mail	262-2323	
	Red Shamrock		000 200	
Date of Inspection		Start/End 7 :	50/10:06	
Inspector Name, COA Dept.	Gibsu an University Tosh Skursgard Contact Phone #/ E-mail 262-2323 Start/End Time 9:50/10:06 Curtis Cherne, Stormwater Quality 505-924-3420/ccherne@cabq.gov			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	5/06,112-2			
Type of Inspection:				
Regular • During stor	rm event • Post-storm event (> 0.5 inch) • 31	11 / Complaint Resp	onse • Follow-Up	
	Weather Information			
Weather at time of this inspect			perature: ~ 45 F°	
		Windy		
Has there been a storm event s Amount: < 1/4" (1/4") 0 3				
	Erosion & Sediment Control Inspect	tion		
Entrance / Track-Out				
 Sediment Controls / Silt F Check Dams, Waddles 				
Erosion Controls / Mulch	, Seed,			
 Housekeeping/Pollutant C 	Controls A	****		
Debris/Pollutants/Sediment in MS4				
• Notes	į)			
Is site being maintained in compliance with the Drainage Ordinance ? Yes No. Cath c chu 4-4-17				
Is site being maintained in complian	nice with the Diamage Ordinance ./ 109 110	VV*	Date	
Signature Date				

ECS File: MISEUL 2



City of Albuquerque Stormwater Construction Site Inspection Report Muy Owner

	General Information			
Project Name and Location	Gibson Rising Gibson & University		C. C.	
Site Contact Name & Agency	Josh Skusgard Per Sharrock	Contact Pho	one # 262 -232	
Date of Inspection	1-4-16	Start/End Time	12:0/12:15	
Inspector Name, COA Dept.	Curtis Cherne	Cherne, Stormwater Quality		
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwater- Stormwater One			
Describe Present Phase of Construction	In grased			
Type of Inspection: Regular · During sto	rm event • Post-storm event • 311/C Weather Information	omplaint Respons	se • Follow-Up	
Weather at time of this inspect • Clear Cloudy Has there been a storm events Amount: • < 1/4" • 4" to	Rain · Sleet · Fog · Snowing ince the site was Permitted? · Yes · No	"	Temperature: ~_ 35_F°	
Check any BMPs that h	ave FAILED or REQUIRE MAINTENAN			
 Entrance / Off Tracking Sediment Controls / Silt I Check Dams, Waddles 	s, etc. alley ghill had At	3M1 51H	Noxt o	
 Erosion Controls / Mulch 	Chu-til va NOB	~D		
• Wind Blown Erosion	Vo			
 Housekeeping / Pollutant 	Controls OH		·	
Is site being maintained in complia	nce with Const. Gen. Permit ?* Yes No	Signature	Ly-U Date	



City of Albuquerque Stormwater Construction Site Inspection Report

The state of the s				
	General Information			
Project Name and Location	Gibson & University Jush 5 Kensgard			
Site Contact Name & Agency	oush 5 Kensgard Red Shanroch	Contact Pho	ne# 262-23 2 7	
Date of Inspection	11-16-15	Start/End Time		
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Qualified Compliance Inspector of Stormwat	er- Stormwater	One	
Describe Present Phase of Construction 2 51 hrs mostly darlynd, one out by				
Type of Inspection:			vn 11 - 77	
Regular • During stor	rm event • Post-storm event • 311 / Com	plaint Respons	e · Follow-Up	
	Weather Information			
_	Rain · Sleet · Fog · Snowing ·	Windy	Temperature: ~ 5/F°	
	ince the site was Permitted? Yes · No 4" · > 34" · Snow"			
	Erosion & Sediment Control Inspec	ction		
Check any BMPs that ha	ave FAILED or REQUIRE MAINTENANCE			
■ Entrance / Off Tracking	de			
 Sediment Controls / Silt F Check Dams, Waddles 		or Erosi	n BAR South M	
 Erosion Controls / Mulch 	, Seed, No.			
Wind Blown Erosion	NO .			
 Housekeeping / Pollutant 	Controls Irw			
		<u>.</u>		
Is site being maintained in complian	nce with Const. Gen. Permit ? Yes (N)	nt - Ch ignature	Date	

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Monday, November 16, 2015 4:07 PM

To:

Josh Skarsgard

Subject:

Gibson rising sediment in University

Attachments:

entrance-university.jpg

Josh,

Seems Gibson Rising is going fairly well. Chili's is done and Chick-Fil-A is close.

I was out there today and noticed that the old haul road south of Chick-Fil-A is depositing sediment into University Blvd. See photo.

R and O is going to clean up University adjacent to their site.

There are a few ways to fix this.

- 1. Riprap/rock similar to a construction entrance. May fill-up and have to be maintained.
- 2. Construct a compacted berm to prevent flows from entering University Blvd.
- 3. A large wattle may work if it is toed in.

Thanks,

Let me know if you have any questions.

Curtis

924-3420

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Monday, January 04, 2016 4:17 PM

To:

Josh Skarsgard

Cc:

grant@inspectionsplusinc.com

Subject:

gibson rising out-lot

Attachments:

west-edge.jpg; nw-corner.jpg; SE-corner.jpg; site.jpg

Josh,

I was out at Gibson Rising today during my tour of that part of town.

The out-lot that was going to be McDonalds is dirt. Some of this dirt will leave when it rains and end up in the storm drains in University Blvd. I would like to prevent that.

I noticed that Chick-Fil-A is busy and they want to use this area for overflow parking, so a silt fence or wattle along the edge probably wouldn't work. I recommend putting down some gravel (3/4 inch crushed) to stabilize the dirt. If you don't wish to gravel the entire lot, an area, say 20 feet wide along the western and southern edges may work. This would at least provide some filtering. Of course it may require maintenance, whereas gravelling the entire lot would not require any. If you wish to see a good example, check out Heritage Marketplace at Unser and Ladera.

Chick-Fil-A customers would probably prefer parking on gravel than on dirt anyway.

The NPDES CGP allows 14 days for stabilization. This seems a reasonable time frame.

If you have another suggestion, please let me know.

Curtis Stormwater Quality 924-3420

ECS File: MISE012



City of Albuquerque Stormwater Construction Site Inspection Report

	General Informat			
Project Name and Location	ann east of chick, Gibson and Convising	ESC PERMIT #		
Site Contact Name & Agency	Ped Shamode	Contact Phone #		
Date of Inspection	8-25-15	Start/End 7	25/9:15	
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality			
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov			
Inspector Qualifications	Stormwater USA			
Describe Present Phase of Construction rough ground pound curb an guth				
Type of Inspection: Regular · Drive-By/Random · During storm event · Post-storm event · 311 / Complaint Response				
Weather Information				
Weather at time of this inspection? Clear • Cloudy • Rain • Sleet • Fog • Snowing • High Winds • Other:				
Has there been a storm event since the site was Permitted? Yes · No				
Amount: • < 1/4" • 1/4" to 3/4" Intensity: • Light • Med. • Hvy. • Snow"				
	Erosion & Sediment Contr	ol Inspection		
Check any BMPs that h	ave FAILED or REQUIRE MAINTE	NANCE		
Entrance / Off Tracking				
Sediment Controls / Silt Fence, Check Dams, Waddles, etc.				
Erosion Controls / Mulch, Seed,				
• Wind Blown Erosion				
Housekeeping / Pollutant Controls Concrete wash out a middle of forth				
· Lots of Arask				
Is site being maintained in compliance with Const. Gen. Permit?* Yes Oo Gignature Permit Property Date				

Cherne, Curtis

From: Cherne, Curtis

Sent: Tuesday, August 25, 2015 2:22 PM

To: Josh Skarsgard

Cc: jeff@inspectionsplusinc.com
Subject: SWPPP inspection Gibson Rising
Attachments: concrete-washout.jpg; trash2.jpg

Josh,

Good afternoon,

Stopped by Gibson Rising today for a SWPPP inspection. It's a triple out there with the Chili's and Chick-Fil-A. I spoke with Trish a few minutes ago concerning the inspection results, but I also like to follow up with an e-mail to document the communication.

There was a concrete wash-out in the middle of the site and quite a bit of trash laying about. As is normal, the issues mentioned above are to be mitigated within 7 days.

Thanks,

And,

As the Chick-Fil-A progresses and gets finished, you will have to adjust the BMPs (new silt fence/wattles) on the old McDonald's site, which is why I copied Jeff on this e-mail.

If you have any questions please let me know.

Curtis Cherne, PE Stormwater Quality COA 924-3420