ECS	S Fi	le:	
-----	------	-----	--



ESC PERMIT #				
	423-847-701			
Start/End 7!5	ss/ro:es			
Curtis Cherne, Stormwater Quality				
enstruck t	bleg now complete			
event • 311/0	Complaint Response			
Tem igh Winds • Ot • Hvy.				
on				
. /				
to a cha	€-∂5- 1/ Date			

NPDES Tracking No: NARD BLIB

ECS File: M 15E a 28



	General Information					
Project Name and Location	Chilis Gibson & University	ESC PERM	IT#			
Site Contact Name & Agency	chilis		ne#	423-847-787 ⁴		
Date of Inspection	8-7-15	Start/End Time	10:	35/		
Inspector Name, COA Dept.						
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Stormwater USA					
Describe Present Phase of Construction						
Type of Inspection:			211 //	CI-i D		
· Regular · Drive-By/R	andom • During storm event • Post-sto	rm event • :	31170	Complaint Response		
	Weather Information					
Weather at time of this inspect · Clear Ooudy	ion? Rain · Sleet · Fog · Snowing ·	High Winds		perature: ~ &O F° her:		
I .	ince the site was Permitted? · For · No					
Amount: • < 1/4" • 1/4" to 3				• Snow'"		
	Erosion & Sediment Control Inspe	ction				
Check any BMPs that ha	ave FAILED or REQUIRE MAINTENANCE	2				
Entrance / Off Tracking	9007					
Sediment Controls / Silt Fence, Check Dams, Waddles, etc. Ood fred previous when at NW Corner						
• Erosion Controls / Mulch, Seed,						
• Wind Blown Erosion						
Housekeeping / Pollutant Controls 3 Concrete wash-outly one has drained						
· Still som frash outsile princh force but was midisales w/						
Is site being maintained in complia	nce with Const. Gen. Permit? Yes No S	s	-	8-7~ 1 Date		



	, General Information				
Project Name	CMIIS	1			
and Location	Chili's Gibsur & Universit Kevin Moynihan Buffalo Cunstructur UC	B			
	Kevin Moynitan	Contact Phone #/			
Site Contact Name & Agency	Rulling Cuchuch UC	E-mail			
Date of Inspection	4-4-17				
		Time 9!SU 918/			
Inspector Name, COA Dept.	Curtis Cherne, Stormwater Quality /				
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov Qualified Compliance Inspector of Stormwater- Stormwater One				
Inspector Qualifications Describe Present		ater-Stormwater One			
Phase of Construction	Stabilize ?				
Type of Inspection:					
Regular • During stor	m event • Post-storm event (> 0.5 inch) •	311 / Complaint Response • Follow-Up			
	Weather Information				
Weather at time of this inspecti		Temperature: ~ 45 F°			
	Rain · Sleet · Fog · Snowing	Windy			
Has there been a storm event si Amount: • < 1/4" • 1/4" to 3	nce the site was Permitted? · Yes · No 4" · > 34" · Snow	>>			
Amount. 74 74 10 7	Erosion & Sediment Control Insp				
	Erosion & Seamicine Control Insp	cetton			
 Entrance / Track-Out _ 	NU				
 Sediment Controls / Silt F Check Dams, Waddles 	. A1.				
 Erosion Controls / Mulch, 	Seed, Scare, pands				
 Housekeeping/Pollutant C 	ontrols $\mathcal{O}\mathcal{U}$				
Debris/Pollutants/Sediment	nt in MS4				
Notes JV1	previous post constru	who vosa 1854			
	- 1				
Is site being maintained in complian	ce with the Drainage Ordinance? Yes No	Signature Chy 4-4-17 Date			

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Friday, August 07, 2015 12:40 PM

To:

kevin.moynihan@buffaloconstruction.com; rachel.steele@buffaloconstruction.com

Subject:

Chili's on Gibson SWPPP follow-up inspection

Attachments:

concrete-washout-center.jpg; concrete-washout-gibson.jpg; concrete-washout-se-corner.jpg

Kevin,

I went out to the site today for a follow-up inspection due to last week's issues.

The items were addressed satisfactorily. Thank you.

However, looks like you had some recent concrete work done and you had three wash-outs.

The concrete wash-out near Gibson Blvd has run to the other side of the perimeter fence. It got caught by the silt fence. A bit close to entering our storm drain system.

I did notice you have a concrete wash-out station on-site. It just needs to be used.

Looks like you've got forms setup for some curb work. Please remind concrete person to use wash-out bin.

Per standard mitigation time, I expect the concrete wash-outs to be cleaned up within seven days.

See ya in about a week.

Curtis Cherne, PE Stormwater Quality COA 924-3420 NPDES Tracking No: NAPID B 6/8



	General Information					
Project Name and Location	Chiti's Gibson and University	ESC PERMIT #		~14		
Site Contact Name & Agency	Kevin Moynihan Bullato Construction, Inc		ne#	423 - 847 - 7874		
Date of Inspection	7-30-15	Start/End 9:55 /10:20				
Inspector Name, COA Dept. Curtis Cherne, Stormwater Quality						
Inspector Phone / E-mail	505-924-3420/ccherne@cabq.gov					
Inspector Qualifications	Stormwater USA					
Describe Present Phase of Construction						
Type of Inspection: Regular Dive-By/R Follow-Up	andom • During storm event • Post-sto	orm event •	311 /	Complaint Response		
	Weather Information					
	Rain · Sleet · Fog · Snowing ·	High Winds		perature: ~_ 75 F°		
Has there been a storm event s Amount: • < 1/4" • 1/4" to 3	ince the site was Permitted? · Yes · No 'A" · Suran Intensity: · Light · M	ed. • Hvy.		• Snow"		
	Erosion & Sediment Control Inspe	ection				
 Check anv BMPs that have a compared to the controls of the controls of the controls of the controls of the control of the contro		but dra	cha	back into 5th		
Erosion Controls / Mulch	, Seed, ~0					
Wind Blown Erosion	~0					
Housekeeping / Pollutant	Controls trash along 6.650	h				
Is also being registered in complic	ance with Const. Gen. Permit ?" Yes	Cent: ch		7-2-4		
is site being maintained in compila		Signature		Date		

Cherne, Curtis

From:

Cherne, Curtis

Sent:

Thursday, July 30, 2015 11:47 AM

To:

'kevin.moynihan@buffaloconstruciton.com'; 'rachel.steele@buffaloconsgtruditon.com'

Subject:

SWPPP inspection Chili's 1700 Miles Rd

Attachments:

clogged-inlet.jpg; culvert-wattle.jpg; swept-street.jpg; trash.jpg

Kevin,

Thank you for taking the time with me this morning.

The following SWPPP issues were found at the site this morning:

- 1. The inlet just upstream of the channel was not visible. It is difficult to tell if it is totally plugged or protected. The approved plan shows inlet protection around the inlet. This is a better way to go than covering it as it could still except some drainage. I want to see the inlet during my follow-up visit.
- 2. The wattle at the sidewalk culverts was not covering the western culvert and the culvert is plugged.
- 3. There was some trash along the northern edge of the property.

Gibson Blvd appeared to be swept recently. Thank you.

As mentioned onsite, the above listed items are to be mitigated within 7 days.

If you have any questions, you can contact me at 924-3420.

Curtis Cherne, PE Stormwater Quality Engineer City of Albuquerque