

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	M15E				Mister Car Wash #1394		
NPDES Id. No.	NMR10				2161 Gibson Blvd SE		
9/6/2023		Owner			Contractor		
Operator		CWPS Corp, a Delaware Corporation			Texana Builders		
Contact name & title		Prabhs Matharoo			Damian Toth		
e-mail		pmatharoo@mistercarwash.com			damian@texanabuilders.com		
Contact Phone #		520-615-4000			832-704-8484		
COA Inspector		Chancellor English			Start/End Time: 3pm		
Construction Phase:		-			ading, utilities		
	nspection:	Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
	er at time of i		Cle		Temper		95
	date of last s			.ai	i iemper	8/8/2023	55
		0.25					
Item			Deficier	ncy/ Correctiv	ve Action		
Number							
1	1 Certification signatures are missing in the SWPPP according to CGP Appendix G, Part G.11.2. The S map is out-of-date in violation of CGP Part 7.4.1. Required mitigation: CGP Appendix G, Part G.11						
	states that the SWPPP, any SWPPP modifications, inspection reports, corrective actions, and other						
	compliance documentation must be signed by the operators or a duly authorized representative. Ar individual is a duly authorized representative if the authorization is made in writing (signed, dated, a						
	included in the SWPPP) by the operators and the authorization specifies either an individual or a						
	position having responsibility for the overall operation of the facility, such as the on-site superintend (Note: the duly authorized representative cannot be a subcontractor or third-party.) You must modi your SWPPP within 7 days whenever you make changes to your construction plans, stormwater contr						
	or other activities at your site that are no longer accurately reflected in your SWPPP as per CGP Part						
	7.4.1.						
	7.4.1.						
2	There was sed	iment trackou	ut on the access r	oad and along	Miles Rd to th	e south of the pro	perty by
_	There was sediment trackout on the access road and along Miles Rd to the south of the property by vehicles still using an old construction entrance on the southwest corner with no controls in violation of						
	-						
	CGP Part 2.2.4. Required mitigation: You must restrict vehicle use to properly designated exit points						
	and use appropriate stabilization techniques at all points that exit onto paved roads per CGP Part 2.2.4 This Part also requires that sediment that has been tracked-out from your site onto paved roads, sidewalks, or other paved areas outside of your site be removed by the end of the same business day i which the track-out occurs and to remove by sweeping, shoveling, or vacuuming.						
	which the trac	ck-out occurs a	and to remove by	sweeping, sno	overing, or vacu	uuming.	
3	Concrete wash	nout was foun	d adjacent to the	nerimeter silt	fence in violat	tion of 2 3 4 Requ	uired
	Concrete washout was found adjacent to the perimeter silt fence in violation of 2.3.4. Required mitigation: You must direct washwater into a leak-proof container or leak-proof and lined pit and do						
	-			-		-	-
	not allow liquid wastes to be disposed of through infiltration or to otherwise be disposed of on the						
	ground as per CGP Part 2.3.4.						
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspect	tion Reports	No	Latest re	port Date:	NA	
Notes	1						
Notes:							

City of Albuquerque Stormwater Inspector Signature and date: 9/13/2023 Contact information: Chancellor English (505) 924-3325 cenglish@cabq.gov

Chancellor English