

## City of Albuquerque Stormwater Construction Site Inspection Report

			General Ir	ntormation			
Project Nar	ne:	Volterra Uni	t 3				
Location:		Juan Tabo and Cavalcade					
Site Contact Name & Agency		Eddie Loven - LGI Homes ESC Fil			M22E016C		
		eloven@lg	ihomes.com	NPDES Id. No.		NMR1000AZ	
Inspection	Date:		Start/End Time: 13	35/1400hrs			
	water Inspectoi	r:	Timothy E. Sims				
	ction Phase:			_	_		
Type of In	spection: x	Regular	Storm Event	Post Storm I	Event >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~ 84*							
Estimated date of last storm 0.25" or greater							
Item	Definion and Commenting Action						
Number	Deficiency/ Corrective Action						
1	Please provide latest SWPPP self-inspection report.						
2	Waste construction and domestic not in acceptable waste container. Please mitigate.						
	·						
3	1636 Gulfport and the lot to the south has washout not in acceptable container. Please have						
	trades utilize provided washout.						
4	Material storage, sheetrock, is required to be in weather proof location. Please mitigate.						
2.1	Discharge off site?	(Y/N)	No				
4	Self Inspect	ion Reports	requested	Latest rep	oort Date:	6/7/20	19
Notes:							

 $\label{lem:city} \textbf{City of Albuquerque Stormwater Inspector Signature and date:}$ 

Contact information: Timothy E. Sims - (505) 803-6155

tsims@cabq.gov

08/12/19