

## City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

Project Name:		Volterra Unit3					
Location:		Juan Tabo and Cavalcade					
Site Contact Name & Agency	Eddie Love, Jake Vautier			ESC File No.	M22E016C		
	LGI Homes			NPDES Id. No.	NMR1000AZ		
Inspection Date:	05/29/19	Start/End Time:	9:00	9:45			
CoA Stormwater Inspector:		Curtis Cherne					
Construction Phase:		Constructing Homes					
Type of Inspection:	X	Regular	Storm Event	Post Storm Event >0.25"	311/Complaint	Follow Up	

Weather at time of inspection?	Clear/ Windy	Temperature: ~	60
Estimated date of last storm 0.25" or greater	5/10/2019		

Item Number	Deficiency/ Corrective Action			
1	Numerous washouts at the site: lot across the street from 1612 Volpani, 1624 Gulf Stream, 1608 Gulf Stream, subdivision washout facility lot			
2	Constructon and domestic waste(s) not in an acceptable container			
3	require sediment BMP 1624 Gulf Stream and adjoining lots			
2.1	Discharge off site? (Y/N)	No		
4	Self Inspection Reports	request	Latest report Date:	2/15/2019

Notes:	
Block in subdivision wash-out facility is most likely the cause of the concrete truck driver washing out next to it.	

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Curtis Cherne PE, 505-924-3420  
[ccherne@cabq.gov](mailto:ccherne@cabq.gov) 05/29/

05/29/19 Ante G. Chenn