

## City of Albuquerque Stormwater Construction Site Inspection Report

## General Information

|                            |             |                         |               |                         |               |   |           |
|----------------------------|-------------|-------------------------|---------------|-------------------------|---------------|---|-----------|
| Project Name:              |             | Volterra Unit 3         |               |                         |               |   |           |
| Location:                  |             | Juan tabo and Cavalcade |               |                         |               |   |           |
| Site Contact Name & Agency | Eddie Loven |                         | ESC File No.  |                         | M22E016C      |   |           |
|                            | LGI Homes   |                         | NPDES Id. No. |                         | NMR1000AZ     |   |           |
| Inspection Date:           | 06/14/19    | Start/End Time:         | 1:30/2:00     |                         |               |   |           |
| CoA Stormwater Inspector:  |             | Curtis Cherne           |               |                         |               |   |           |
| Construction Phase:        |             | Constructing Homes      |               |                         |               |   |           |
| Type of Inspection:        |             | Regular                 | Storm Event   | Post Storm Event >0.25" | 311/Complaint | X | Follow Up |

|   |              |                |    |
|---|--------------|----------------|----|
| Weather at time of inspection?                | Clear/ Windy | Temperature: ~ | 85 |
| Estimated date of last storm 0.25" or greater | 5/10/2019    |                |    |

| Item Number | Deficiency/ Corrective Action  |    |                     |          |
|-------------|--|----|---------------------|----------|
| 1           | Construction and domestic waste on lot across the street from 1619 Borrego |    |                     |          |
| 2           | sediment BMP (cutback) 1600 Volponi  |    |                     |          |
| 3           | replace cover on waste container and fix it                                |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
|             |  |    |                     |          |
| 2.1         | Discharge off site? (Y/N)  | No |                     |          |
| 4           | Self Inspection Reports  |    | Latest report Date: | 6/7/2019 |

|        |  |
|--------|--|
|        |  |
| Notes: |  |
|        |  |
|        |  |
|        |  |
|        |  |
|        |  |

City of Albuquerque Stormwater Inspector Signature and date:  
Contact information: Curtis Cherne PE, 505-924-3420  
[ccherne@cabq.gov](mailto:ccherne@cabq.gov) 06/14/2024

06/14/19

Carta a Cheme