

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
ESC File No.	M21E0	D15B Project Name:			Volterra - Unit 3			
NPDES Id. No.	NMR1000AZ		ocation:		Juan Tabo and Cavalcade Dr.			
4/19/2021		Owner			Contractor			
Operator		LGI Homes			LGI Homes			
Contact name & title		Eddie Loven			Dale Works			
e-mail		eloven@lgihomes.com			Dale.Works@lgihomes.com			
Contact Phone #		505-991-0807			505-379-3822			
COA Inspector					Start/End Time:	: 12:25 PM/1:00 PM		
	ction Phase:				rtical			
Type of Inspection:		Regular	Storm Event	Past Storm I	Event >0.25"	311/Complaint	Follow Up	
	er at time of i			r	Temperature: ~ 70			
Estimated date of last storm 0.25" or greater 2/22/2021								
Item								
	Deficiency/ Corrective Action							
Number								
1	Maintain/replace inlet protection							
2	Clean trackout and remove dirt from sidewalks							
3	Remove and dispose of washout							
4	Secure trash bins and provide covers							
5	Clean washout area							
6	Repair/replace silt fences							
				-				
			•					
2.1	Discharge off site?	(Y/N)	no					
4	Self Inspect	tion Reports	Requested	Latest rep	oort Date:	last we	ek	

Notes:	Spoke with Dale (Foreman). He emailed Superior earlier today regarding fixing the inlet
protection	n controls. He confirmed that the last self-inspection was conducted last week.
We discus	ssed the issues above that need mitigation. SWPPP is held at their office.

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Thomas Evans (505-803-6215)

tevans@cabq.gov

Thomas Evans 04/21/2021