

City of Albuquerque Stormwater Construction Site Inspection Report

General Information								
Project Nar	ne:	Juan Tabo Hills Estates						
Location:		Juan Tabo and Tijeras Arrojo						
Site Contact Name &		Bob Feeney		ESC File No.		M21E018		
Agency		Raylee Homes		NPDES Id. No.		NMR1001A4		
Inspection		5.23.19	Start/End Time:	1:00	3:00			
CoA Stormwater Inspector: Curtis Cherne								
	tion Phase:	constructing scour wall						
Type of Inspection: X		Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up	
							70	
Weath	er at time of	inspection?	Clear/	Windy	Temper 5/10/2019	rature: ~	70	
Estimated	date of last:	storm 0.25"	or greater		3/10/2019			
Item	Definion and Connection Action							
Number	Deficiency/ Corrective Action							
The same of the same of	numerous wash-outs							
1								
2	rock filter downstream of pond is full and is being bypassed on north end							
						-		
		<u></u>						
			-					
						··		
	_							
					 .			
2.1	Discharge off site?	(Y/N)	No					
4	Self Inspec	tion Report	s	Latest re	port Date:	5/10/20	019	
Notes:								
				******	<u> </u>		-	
<u> </u>			-					

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

5.23.19

auto a chem