

## City of Albuquerque Stormwater Construction Site Inspection Report

| General Information  |  |                              |           |                             |   |                    |     |  |
|--|--|------------------------------|-----------|-----------------------------|---|--------------------|-----|--|
| ESC File No.   | M21E0  | _ ,                          |           | Volterra - Juan Tabo Hills  |   |                    |     |  |
| NPDES Id. No.  | NMR1   |                              |           |                             | 11404 Rock Squirrel Ave SE                      |                    |     |  |
| 1/12/2022  |  | Owner/Contractor             |           | DA ?                        |   |                    |     |  |
| Operator   |  | Twilight Homes               |           | Alex Cronnen                |   |                    |     |  |
| Contact name & title   |  | Tim Mcnaney                  |           | Alex Grannan                |   |                    |     |  |
| e-mail   |  | tmcnaney@twilighthomesnm.com |           | agrannan@mtventerprises.com |   |                    |     |  |
| Contact Phone #  |  | 505-975-1154                 |           |                             |   |                    |     |  |
| COA Inspector<br>Construction Phase:   |  | James Hughes                 |           | Start/End Time              | e: 10:00  | 10:00am            |     |  |
| Type of Ir   | spection:  |                              |           |                             | ertical<br>Event >0.25" 311/Complaint Follow Up |                    |     |  |
|  |  |                              |           |                             |   |                    | 39  |  |
| Weather at time of inspection?clearTemperature: ~ 39Estimated date of last storm 0.25" or greater10/1/2021 |  |                              |           |                             |   |                    | 33  |  |
|  |  |                              |           |                             |   |                    |     |  |
| Item   | Deficiency/ Corrective Action  |                              |           |                             |   |                    |     |  |
| Number   |  |                              |           |                             |   |                    |     |  |
| 1  | Washout on lots on Monzano Vista Ave.and Lobo Trout Ct.                                |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
| 2  | Sediment trac  | kout on Monzano Vista Ave.   |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
| 3  | SWPPP not up-to-date. (Sold lots and IP not on map, Operator C                         |                              |           |                             |   |                    |     |  |
|  | signature missing from reports and reports not current, Deligations of authority don't |                              |           |                             |   | ithority don't mee | et  |  |
|  | requirements of CGP App 'I.11'   |                              |           |                             |   |                    |     |  |
| 4  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
|  |  |                              |           |                             |   |                    |     |  |
| 2.1  | Discharge off site?  | (Y/N)                        | no        |                             |   |                    |     |  |
| 4  | Self Inspec  | tion Reports                 | Requested | Latest re                   | port Date:                                      | 4/7/20             | 021 |  |

| Notes:                                | Posting was OK, SWPPP at sales model. Reports missing. |  |  |  |  |
|---------------------------------------|--|--|--|--|--|
| Self inspection reports not received. |  |  |  |  |  |
|                                       |  |  |  |  |  |
|                                       |  |  |  |  |  |
|                                       |  |  |  |  |  |

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Jamed Hughes 505-924-3420 jhughes@cabq.gov 1/14/22

James D. Hughes