

City of Albuquerque Stormwater Construction Site Inspection Report

			General I	nformation				
ESC File No. N08E006F		006F P	roject Name:	Aspire Subdivision Units 1-4				
NPDES Id. No.	NINIR1003RD		ocation:	11000 Colobel Ave NW				
1/22/2021		Owner		Contractor				
			s Development,					
Contact name & title		Garret Price		Scott Stephen				
e-mail		gprice@priceldg.com		ssteffen@priceldg.com				
Contact Phone #		304-8473		243-3949				
COA Inspector		Doug Hughes		Start/End Time: 10am				
Construction Phase:				frastructure nearly complete				
	nspection:	Regular	Storm Event	Post Storm Event >0.25" 311/Complaint Follow Up				
	er at time of i		Cle					
Estimated	date of last s	storm 0.25" o	r greater	2/22/2021				
Item			Deficien	nul Corrective Action				
Number	Deficiency/ Corrective Action							
	construction	not started vet	Reason for inst	pection is to check stabilization from previous 2004				
	construction not started yet. Reason for inspection is to check stabilization from previous 2004							
	development. The ground cover is more than 70% of natural undisturbed cover.							
	First 100' Transect is offsite 300' west of the intersection of 118th St./Amole Mesa Ave SW. Grass is							
	conspicuously absent, only sage (3 pnt) and litter (3 pnt) Oak ?dead (1pnt)							
	7 pnt cover/34 pnt total= 20% cover							
				te sampling points every 3' - 34 points total Grass (3pnt) % of natural undisturbed.				
2.1	Discharge off site?	(Y/N)	no					
<u> </u>	-	tion Reports	110	Latest report Date:				
	I Solt Inchoc	TIAN PANARTC	1					

Notes:			

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov

3/25/2021

James D. Hughes