

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Name:		Valle De At	Valle De Atrisco Apartments				
Location:		10001 Ceja		ESC File No.			
Site Contact Name &		Trevor Wis	Trevor Wismann			P09E002D	
Agency		Trevco Inc	Trevco Inc			NMR1001TV	
Inspection		06/11/19	Start/End Time:	8:55/9:30			
	water Insped		Curtis Cherne				
	ction Phase:		vertical				
Type of Inspection:		Regular	Regular Storm Event		Event >0.25" 311/Complaint X Follow Up		
Weather at time of inspection? Clear Temperature: ~ Estimated date of last storm 0.25" or greater 5/10/2019							65
Estimated	date of las	st storm 0.25'	or greater		5/10/2019		
Item	D. C. t. and C. and A. A. A.						
Number	Deficiency/ Corrective Action						
	City fance did not out and to north adde of site						
1	Silt fence did not extend to north edge of site						
2	constrution waste not in an acceptable container NE corner of site						
3	silt fence required maintenance south of entrance						
	-						
				···			
						-	
		- **					
				· · · · · · · · · · · · · · · · · · ·			
١ .							
2.1	Discharge off sit	e? (Y/N)	No			6-6	-19
4	_	ection Repor		Latest re	port Date:	3/13/20	
	Sell ilish	- Repor	15	Latestile	port bate.	-5/15/20	71.7
Notes:							
They had installed new silt fence north of entrance, but did not go far enough							
					-		
							-

City of Albuquerque Stormwater Inspector Signature and date:

Contact information:

Curtis Cherne PE, 505-924-3420

ccherne@cabq.gov

06/11/19 Cut c chen