

## City of Albuquerque Stormwater Construction Site Inspection Report

			General Information					
Project Name and Location		Valle B	le Adrisco Ap Ceja Visla	continuts				
		10010	Ceja VISJA	P& DW				
Site Contact Name & Agency		Todd Co	trisco Apts, CIC	ESC File No. NPDES ID No.	P09E00213			
Date of Inspection		12-10-18 Start/End 12:15/1.00						
COA Inspector Name		Curtis Cherne, Stormwater Quality						
Describe Present Phase of Construction		Constructing access Rd at 98th						
	nspection: lar • During stori		storm event (> 0.25 inch) • 3		ponse · Follow-Up			
			Weather Information					
	at time of this inspection		Fog · Snowing ·	Tem Windy	perature: ~F°			
Has there	been a storm event si	nce the site was Pe	ermitted? (Ye) No					
Amount:	< 1/4" to 3/4	• > 3/4"	• Snow"					
	0		Inspection					
CGP <sup>1</sup> Section	BMP / Activity	Maintenance or Corrective Action Required		Location and Notes				
1.5	Post a Notice							
2.2.1	Provide and maintain Natural buffer when Waters of the US < 50 ft							
2.2.3	Sediment control along any perimeter	+	Sitt fora North.	ide tust w	Rd Low spot			
2.2.3	Sediment control along any perimeter	V	require Sediment	BMP access	Rd Low Spot			
2.2.3	Sediment control along any perimeter				•			
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.3	Sediment control along any perimeter							
2.2.4	Minimize sediment track	-	No treck anythory on	15t Location -	ner he in my			

2.2.5	Manage stockpiles			
2.2.6	Minimize Dust			
2.2.10	Protect Storm Drain Inlets			
2.2.10	Protect Storm Drain Inlets			
2.2.11	Minimize erosion of conveyance channels			
2.2.12	Sediment Basins			
2.2.14	Stabilize exposed portions of the site.			
2.2.14	Stabilize exposed portions of the site.			
2.2.14	Stabilize exposed portions of the site.			
2.2.14	Stabilize exposed portions of the site.			
2.3.1	Equipment and Vehicle Fueling	·		ti .
2.3.2	Equipment and Vehicle Washing			
2.3.3	Building Material Storage			
2.3.3	Fuel, oil, hydraulic fluid, petroleum products and chemical storage			
2.3.3	Construction and Domestic Wastes			waste containe not covered no cover present
2.3.3	Construction and Domestic Wastes			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.			
2.3.4	Washing Applicators used for paint, stucco, concrete, etc.			
2.4	Dewatering			
2.1	Discharge off site?	· Yes · No		
4	Self-Inspection Reports			Latest Report Date:
	ty Inspector Use) Items in ction General Permit (C		n	be left blank.

Maintenance or corrective actions are to be completed within 7 days.

Notes:	
Surveyor.	nahinda 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
COXIVE STA	and Duris chart, the is no LTC. Roal
graw o	ut SE winn
octive octive	ly watering sile

Contact Info: Curtis Cherne, 505-924-3420, ccherne@cabq.gov