

City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ECS File No.	P09E002D CV	Project Name:	Ceja Vista Unit 1
NPDES Id. No.	NMR100ZBE	Location:	9800 Dsennis Chavez SW
12/29/2020	Dennis Chavez	Contractor	
Operator	Ceja Vista LLC	Franklins	
Contact name & title	Bill Allen manager	Gus Harbaugh	
e-mail	ballen@westpacnm.com	Gus.Harbaugh@feinm.com	
Contact Phone #	505-440-7262	w796-5457 m975-2864	
COA Inspector	Doug Hughes	Start/End Time:	8am
Construction Phase:	infrastructure complete		
Type of Inspection:	Regular	Storm Event	Post Storm Event >0.25"
		311/Complaint	Follow Up
Weather at time of inspection?	Cloudy	Temperature: ~	40
Estimated date of last storm 0.25" or greater	12/11/2020		
Item Number	Deficiency/ Corrective Action		
1	Silt fence down and full of sediment reset all and add more along Dennis Chaves		
2	Remove sediment from street and sidewalk.		
3	Stabilize all disturbed areas		
4	Provide self inspection reports		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	Requested	Latest report Date: 2/12/2020

Notes:	

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Doug Hughes (505) 924-3420
jhughes@cabq.gov