



City of Albuquerque Stormwater Construction Site Inspection Report

General Information

ESC File No.	P09E002D_CV	Project Name:	Ceja Vista Unit 1
NPDES Id. No.	NMR1002BE	Location:	9800 Dennis Chavez SW
6/4/2021	Owner	Contractor	
Operator	Ceja Vista, LLC	Franklins	
Contact name & title	Bill Allen - Manager	Gus Harbaugh	
e-mail	ballen@westpacnm.com	Gus.Harbaugh@feinm.com	
Contact Phone #	505-440-7262	505-975-2864	
COA Inspector	Thomas Evans	Start/End Time:	10:00 AM-10:25 AM
Construction Phase:	Inactive/temporary stabilization		
Type of Inspection:		Storm Event	Past Storm Event >0.25" 311/Complaint Follow Up
Weather at time of inspection?	clear	Temperature:	~ 76
Estimated date of last storm 0.25" or greater	5/31/2021		
Item Number	Deficiency/ Corrective Action		
1	Silt fence needs maintenance. Repair/replace downed silt fence.		
2	Sediment in street. Sweep and remove sediment from the streets daily.		
3	Sediment accumulated at inlets. Maintain inlet protection and remove sediment.		
4	Areas appear to not be stabilized. Implement temporary stabilization measures.		
5	Self-inspection reports not submitted when last requested.		
2.1	Discharge off site? (Y/N)	no	
4	Self Inspection Reports	Requested	Latest report Date: 2/12/2020

Notes:	No activity on site. The DOT right-of-ways have been mulched.

City of Albuquerque Stormwater Inspector Signature and date:
Contact information: Thomas Evans (505-803-6215)
tevans@cabq.gov

Thomas Evans 06/08/2021