

City of Albuquerque Stormwater Construction Site Inspection Report

	M E K Star		General	Information			
ESC File No.	P09E002	2D CV P	Project Name:		Ceja Vista Unit 1		
NPDES Id. No.		NMR1002BE Location: 9800 Dennis Chavez SW					
6/2	1/2021	Owner			Contractor		
Operator		Ceja Vista, LLC		Franklins			
Contact name & title		Bill Allen - Manager			Gus Harbaugh		
e-mail		ballen@westpacnm.com			Gus.Harbaugh@feinm.com		
Contact Phone #		505-440-7262			505-975-2864		
		Thomas Eva	nas Evans		Start/End Time:	10:55 AM-11:10 AM	
Constru	ction Phase:			Inactive/tempo	orary stabilizatio	n	
Type of Ir	nspection:		Storm Event	Past Storm	Event >0.25"	311/Complaint Follow L	Jp
Weath	er at time of i	nspection?	cl	ear	Tempera	ture: ~ 84	
Estimated	date of last s	torm 0.25" o	r greater		5/31/2021		
lt aus			-				
Item	Deficiency/ Corrective Action						
Number							
1	No NOI posting. Post signage of NOI permit coverage in a location clearly visible to the public.						
2	Areas appear to not be stabilized. Implement temporary stabilization measures. Self-inspection reports not provided upon last request dated 6/8/2021.						
3	Self-inspectior	n reports not p	rovided upon la	ast request dat	ed 6/8/2021.		
2.1	Discharge off site?	(Y/N) cion Reports	no Requested	Latest re	port Date:	2/12/2020	

Notes:Inspections Plus was on site working. They had repaired the silt fence prior to the inspection.They were actively sweeping the streets and shoveling the sediment out of the gutters. They hadstarted cleaning around the inlets. The crew member was not aware of any plans to begin stabilization.NOI posting was not up.Upon returning to the site on 6/22/2021, the streets and inlet protection werecleaned.The NOI posting was still not up.

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Thomas Evans (505-803-6215) tevans@cabg.gov

Thomas Evans 06/22/2021