

City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Na	me:		outh Arroyo Dr	ainage Impro	vements		
Location:		3801 Universit	y Blvd SE				
Site Contact Name &		Sonya Woodho	ouse Facility Ma	ESC File No.		P15E003	
Agency		sonya woodh	nouse@jabil.co	NPDES Id. No.		NMR1002UF	
Inspection Date:		07/06/20 Sta		9/930am			
CoA Stormwater Inspector: Doug Hughes							
	tion Phase:				Construction		_
Type of Ir	spection:	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
							,,,
Weather at time of inspection? Clear Temperature: ~							78
Estimated	d date of last storm 0.25" or greater 6/1/2020						
Item							
	Deficiency/ Corrective Action						
Number							
1	The extended Low Erosivity Waver expired. Permit coverage is required.						
2.1	Discharge off site?	(Y/N)	no				
3	Self Inspect	tion Reports		Latest rep	ort Date:	n/a	
Notes:							
. 10103.							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov