

City of Albuquerque Stormwater Construction Site Inspection Report

General Information										
Project Na	me:	Jabil/Ethicon South Arroyo Drainage Improvements								
Location:		3801 University Blvd SE								
Site Cont	act Name &	Sonya Woodhouse Facility Mai ESC File No.			P15E003					
A	gencv	sonya woodhouse@jabil.co NPDES Id. No.		NPDES Id. No.	NMR1002UF					
Inspection		07/06/20 st	art/End Time:	9/930am						
	CoA Stormwater Inspector: Doug Hughes									
	ction Phase:				e Constructio					
Type of Ir	spection:	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up			
Weath	er at time of i	inspection?	Clea	r	Tempe	rature: ~	78			
Estimated	date of last	storm 0.25" o	r greater			6/1/2020				
Item										
			Deficienc	y/ Correctiv	e Action					
Number										
1	The Low Eros	ivity Waver exp	pired again. NPDI	ES coverage i	is required ur	ntil final stabelizat	ion.			
			_	_						
2.1	Discharge off site?	(Y/N)	no							
3	-	tion Reports		Latest rep	ort Date:	6/4/20	20			
				- -		, , -				

Notes:			

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Doug Hughes (505) 924-3420 jhughes@cabq.gov

7/6/2020 James D. Hughes