

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Na	me:	Jabil/Ethicon South Arroyo Drainage Improvements					
Location:		3801 University Blvd SE					
Site Contact Name &		Sonya Woodho	ouse Facility Ma	ESC FIIE NO.		P15E003	
Agency		sonya woodi	nouse@jabil.co	NPDES Id. No.		NMR1002UF	
Inspection Date:		07/06/20 Sta		9/930am			
CoA Stormwater Inspector: Doug Hughes							
Construction Phase: Infrastructure Construction  Type of Inspection: Regular Storm Event Post Storm Event >0.25" 311/Complaint Fc							T= 11
Type of Ir	ispection:	Regular	Storm Event	Post Storm I	event >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~ /8							
Estimated date of last storm 0.25" or greater					rempe	6/1/2020	, 0
	date of fast s	101111 U.25 OI	greater			6/1/2020	
Item	Deficiency/Corrective Action						
Number	Deficiency/ Corrective Action						
	The Levy Free	uitu Marramaria	inad again NDC	FC	io wa avviwa al vv	mail fimal stab alimat	iaa
1	THE LOW ETOSI	vity waver exp	ireu again. NPL	ies coverage	is required u	ntil final stabelizat	IOII.
2.4	B: 1	()/())		1			
2.1	Discharge off site?	(Y/N)	no	Lotost #5	ort Data:	C / A / 2 O	20
3	Self Inspec	tion Reports		Latest rep	oort Date:	6/4/20	20
Notes:							
-							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov