

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
Project Na	me:	Jabil/Ethicon South Arroyo Drainage Improvements					
Location:		3801 Universit	y Blvd SE				
Site Contact Name &		Sonya Woodhouse Facility Mai ESC File No.			P15E003		
Agency		sonya woodl	nouse@jabil.co			NMR1002UF	
Inspection Date:		09/25/20 Sta	art/End Time:	12:15			
CoA Stormwater Inspector: Doug Hughes							
	tion Phase:				Construction		
Type of Ir	spection:	Regular	Storm Event	Post Storm E	vent >0.25"	311/Complaint	Follow Up
Weather at time of inspection? Clear Temperature: ~							88
Estimated	date of last s	storm 0.25" or	greater			9/1/2020	
Item							
	Deficiency/ Corrective Action						
Number							
1	Final stabeliza	ition is Comple	te, Please file NO	DT.			
2.1	Discharge off site?	(Y/N)	no				
3	Solf Inchor	tion Reports		Latest rep	ort Dato:	7/9/20	20
3	Sell Hispec	tion reports		Latest Tep	ort Date.	7/3/20	20
Notes:							
<u> </u>							

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Doug Hughes (505) 924-3420

jhughes@cabq.gov