

City of Albuquerque Stormwater Construction Site Inspection Report

General Information												
Project Na	me:	Mesa del Sol Montage Unit 3B										
Location:		University and Strand Loop										
Site Contact Name &		Michael Fietz - The Westway ESC File No. R16E006										
Agency			vestway.com	NPDES Id. No.								
Inspection Date:			tart/End Time: 10	020/1030hrs								
CoA Storm	water Inspector											
	ction Phase:	Utilitiesdry and other										
Type of Ir	nspection: x	Regular	Storm Event	Post Storm	Event >0.25"	311/Complaint	Follow Up					
Weath	er at time of i	nspection?	Clea	ar	Tempe	rature: ~	80*					
Estimated	date of last s	<u>torm 0.25" o</u>	r greater			7/7/2019						
Item												
	Deficiency/ Corrective Action											
Number												
	no issues obse	no issues observed on this inspection										
	***Inlet protection is recommended at this time. Throat and grate BMP protection prevents											
	sediment from entering the drainage outfall system.											
							ľ					
2.1	Discharge off site?	(Y/N)	No									
4	Self Inspect	tion Reports	requested	Latest rep	oort Date:	=						
P		•										

City of Albuquerque Stormwater Inspector Signature and date:

Contact information: Timothy E. Sims - (505) 803-6155