

## City of Albuquerque Stormwater Construction Site Inspection Report

General Information							
ESC File No.	R16E00	_			Mesa del Sol Units 3B and 4A		
NPDES Id. No.	NMR10		Location: Dekooning Loop				
5/14/2024 Owner			Contractor				
Operator	0	Pulte Homes Kevin Patton			Same		
Contact na	me & title	kevin.patton@pultegroup.com					
e-mail Contact Pho	200 #	505-341-8591					
					Start/End Time: 1030am		
COA Inspector  Construction Phase:		0 -			· ·		
			la. = .l		ticals	lass to the	le u
Type of Inspection:		Regular	Storm Event		Event >0.25"	311/Complaint	Follow Up
Weather at time of ins				ar	Temperature: ~ 80 4/1/2024		
Estimated date of last storm 0.25" or greater 4/1/2024							
Item			Doficion	cy/Correctiv	o Action		
Number	Deficiency/ Corrective Action						
1	SWPPP - The self-inspection reports were not signed by the operators signatory in violation of CGP Part						
	4.7.2. Required mitigation: Each inspection report must be signed by the operator's signatory in						
	accordance with Appendix G, Part G.11 of the CGP.						
	accordance with Appendix 0, rait 0.11 of the Cor.						
			1	T			
2.1	Discharge off site?	(Y/N)	no				
4	Self Inspection Report		Yes	Latest rep	oort Date:	5/2/20	24
Nata:							
Notes:							
SWPPP was attached to the posting located at the DeKooning Loop and Strand Loop intersection.							

City of Albuquerque Stormwater Inspector Signature and date: Contact information: Chancellor English (505) 924-3325

cenglish@cabq.gov