# DEVELOPMENT REVIEW BOARD

## Parks and Recreation Department

PR-2021-005816
SI-2021-02066 - EPC FINAL SITE PLAN SIGN-OFF
CONSENSUS PLANNING INC. agent for JB HOLDINGS LLC/ TAKE FIVE CARWASH requests the aforementioned action(s) for all or a portion of: LOT 2-C, COTTONWOOD CROSSING PHASE II zoned MX-L, located at 10084 COORS BLVD NW between COORS BYPASS and SEVEN BAR LOOP containing approximately 0.7876 acre(s). (B-14)
PROPERTY OWNERS: JB HOLDINGS , LLC
REQUEST: DRB SIGN OFF OF EPC APPROVED CAR WASH FACILITY

12-15-2021

I was unable to attend the EPC hearing, so please provide feedback if these Parks items were discussed at EPC:

1. MPOS property is located within 330-ft of the subject site, however 4-3(D)(16)(c) was found to not apply due to the timing of the application. The Open Space commented that the site is particularly vulnerable to erosion"…and wanted "to ensure all run-off will be diverted away from MPOS and the adjacent Lower Corrales Main Canal" and additional buffers during construction."
2. The application and NOD discuss neighborhood comments requesting an upgrade to the landscape buffer. This area is clouded on the Landscape Plan. Is this the final version?
3. The Parks and Recreation Department (PRD) is a partner with the Nature Conservancy who developed a Climate Ready Tree List for Albuquerque. Please swap out trees that are not on the list, and higher water use, with trees that are on the Climate Ready list (here: NMFO Climate-Ready Trees Lists (nature.org)). Raywood Ash is not on the Climate Ready list - please comment if this tree is chosen because landscape buffer areas are intended to be water quality swales.
   In addition, Trees must be recommended by the Official Albuquerque Plant Palette: Official Albuquerque Plant Palette and Sizing List-2018-07-03.xlsx (cabq.gov) per IDO Section 14-16-5-6(C)(4)(b).

DEVELOPMENT REVIEW BOARD

Parks and Recreation Department

# Climate-Ready Trees for Albuquerque

LOCATION TYPE 5
STREETSCAPES







## LOCATION CHARACTERISTICS

Follows "Right Tree in the Right Place"

Soil Volume: Sufficient

No Utility Conflicts

Building Setback: >10'

## RECOMMENDED TREES

| | |
|---|---|
| *Arbutus xalapensis* | Texas Madrone |
| *Celtis reticulata* | Netleaf Hackberry |
| *Cercis canadensis* var. *mexicana* | Mexican Redbud |
| *Cercis reniformis* | Oklahoma Redbud |
| *Cercis canadensis* var. *texensis* | Texas Redbud |
| *Cercis occidentalis* | Western Redbud |
| *Cedrus deodara* | Deodar Cedar |
| *Chilopsis linearis* | Desert Willow |
| *Cotinus obovatus* | American Smoketree |
| *Crataegus ambigua* | Russian Hawthorn |
| *Forestiera neomexicana* | New Mexico Privet |
| *Gymnocladus dioica* | Kentucky Coffeetree |
| *Fraxinus cuspidata* * | Fragrant Ash* |
| *Lagerstroemia indica* | Crape Myrtle |
| *Leucaena retusa* * | Golden-ball Lead-tree* |
| *Maclura pomifera* | Osage Orange |
| *Parkinsonia x* 'Desert Museum' * | Palo Verde hybrids* |
| *Pistacia chinensis* * | Chinese Pistache* |
| *Prosopis glandulosa* * | Honey Mesquite* |
| *Quercus arizonica* | Arizona White Oak |
| *Quercus fusiformis* | Escarpment Live Oak |
| *Quercus gravesii* | Chisos Red Oak |
| *Quercus ilex* | Holly Oak |
| *Quercus muehlenbergii* | Chinkapin Oak |
| *Quercus oblongifolia* | Blue Oak |
| *Quercus suber* * | Cork Oak* |
| *Quercus buckleyi* | Texas Red Oak |
| *Sapindus saponaria var.drummondii* * | Western Soapberry* |
| *Sophora secundiflora* * | Texas Mountain Laurel* |
| *Rhus lanceolata* | Prairie Flameleaf Sumac |
| *Ulmus x* 'Morton' *Accolade™* | Accolade Elm |
| *Ulmus x* 'Frontier' | Frontier Elm |
| *Ulmus parvifolia* * | Lacebark Elm* |
| *Vitex agnus-castus* | Chaste Tree |
| *Zelkova serrata* | Japanese Zelkova |

* These species have further site specific needs outlined in Appendix A - Master List

DEVELOPMENT REVIEW BOARD

Parks and Recreation Department

02-02-2022

The Open Space Division requested “additional buffers during construction”?