HYDROLOGY

K11/D38

K11/D38

CITY OF ALBUQUERQUE DRAINAGE REPORT

ZONE ATLAS NO.	NAME OF CONSTRUCTION	OBSERVER	DATE OBSERVED
K-11	Trip Plex Apt.	William R. Rivera	12-5-78

ADDRESS: 116 ESTANCIA NW.

Reason for Field Check: For the drainage report on this apt. unit.

FINDINGS AND CONCLUSION: there is two finding were both connected to ~~[illegible]~~ facilities. Everything was very good going by the plan.

FOLLOW UP ACTION REQUIRED: No follow-up will be needed because this bldg is final

SKETCH:

William R. Rivera
OBSERVER

THIS MICROIMAGE IS THE BEST POSSIBLE
REPRODUCTION DUE TO THE POOR QUALITY
OF THE ORIGINAL DOCUMENT

PLOT PLAN

NORTH

ESTANZIA

GENERAL NOTES

THIS MICROIMAGE IS THE BEST POSSIBLE REPRODUCTION DUE TO THE POOR QUALITY OF THE ORIGINAL DOCUMENT

PLAN SHOT IN TWO SECTIONS.



AN APARTMENT BUILDING
FOR
MR. + MRS TRUJILLO
ALBUQ., NEW MEXICO

PLANS ARE PRELIMINARY
SHOW THE LOCATION OF
THE SPACES PER CITY
STANDARD.

AREAS SHOWN IN BRACKETS
TO BE GRADED INC.

LEGAL DESCRIPTION

LOT V, OF BERGLAT ADDITION
BERNALILLO COUNTY, NEW MEXICO

NOTICE

ALL COMMERCIAL BUILDINGS ARE REQUIRED TO HAVE A FINAL INSPECTION BY THE FIRE DEPT. BEFORE A CERTIFICATE OF OCCUPANCY IS ISSUED. THE BUILDING(S) OR SPACE(S) SHALL BE COMPLETE AND READY TO OCCUPY. PHONE 766-7537

ALBUQUERQUE
BLDG. DEPT.
JUL 6 1974
U.B.C.
PLAN CHECK
SECTION

THIS MICROIMAGE IS THE BEST POSSIBLE
REPRODUCTION DUE TO THE POOR QUALITY
OF THE ORIGINAL DOCUMENT



THIS MICROIMAGE IS THE BEST POSSIBLE REPRODUCTION DUE TO THE POOR QUALITY OF THE ORIGINAL DOCUMENT

PLAN SHOT IN TWO SECTIONS.



THIS MICROIMAGE IS THE BEST POSSIBLE
REPRODUCTION DUE TO THE POOR QUALITY
OF THE ORIGINAL DOCUMENT

1786

HYDROLOGY

K11/D38

XII/D38

CITY OF ALBUQUERQUE DRAINAGE REPORT

ZONE ATLAS NO.	NAME OF CONSTRUCTION	OBSERVER	DATE OBSERVED
K-11	Trip Plex Apt.	William R. Rivera	12-5-78

ADDRESS: 118 Estancia NW.

Reason for Field Check: For the drainage report on this apt. unit.

FINDINGS AND CONCLUSION: there is two finding when both connects to ~~[illegible]~~ problem. Everything was very good going by the plan.

FOLLOW UP ACTION REQUIRED: No follow-up will be needed because this bldg is final

SKETCH:

William R. Rivera
OBSERVER

THIS MICROIMAGE IS THE BEST POSSIBLE
REPRODUCTION DUE TO THE POOR QUALITY
OF THE ORIGINAL DOCUMENT

PLOT PLAN

NORTH

ESTANZIA

GENERAL NOTES

THIS MICROIMAGE IS THE BEST POSSIBLE REPRODUCTION DUE TO THE POOR QUALITY OF THE ORIGINAL DOCUMENT

PLAN SHOT IN TWO SECTIONS.



AN APARTMENT BUILDING
FOR
MR. + MRS TRUJILLO
ALBUQ, NEW MEXICO

PLEASE ACCURATELY MARK THE LOCATION OF THE SPACES PER CITY STANDARD.

LEGAL DESCRIPTION

NOTICE

ALL COMMERCIAL BUILDINGS ARE REQUIRED TO HAVE A FINAL INSPECTION BY THE FIRE DEPT. BEFORE A CERTIFICATE OF OCCUPANCY IS ISSUED. THE BUILDING(S) OR SPACE(S) SHALL BE COMPLETE AND READY TO OCCUPY.
PHONE 766-7537

ALBUQUERQUE
BLDG. DIV.
JUL 6 1978
U.B.C.
PLAN CHECK
SECTION

THIS MICROIMAGE IS THE BEST POSSIBLE REPRODUCTION DUE TO THE POOR QUALITY OF THE ORIGINAL DOCUMENT



THIS MICROIMAGE IS THE BEST POSSIBLE REPRODUCTION DUE TO THE POOR QUALITY OF THE ORIGINAL DOCUMENT

PLAN SHOT IN TWO SECTIONS.



THIS MICROIMAGE IS THE BEST POSSIBLE
REPRODUCTION DUE TO THE POOR QUALITY
OF THE ORIGINAL DOCUMENT