

CITY OF ALBUQUERQUE



September 5, 2012

D. Mark Goodwin, P.E.
Mark Goodwin & Associates, P.A.
P.O. Box 90606
Albuquerque, NM 87199

mark@goodwinengineers.com

**RE: Saltillo Unit II, W.O. # 773481, (A-10/D007)
Engineers Certification - Release of Financial Guaranty—Unaccepted
Engineers Stamp dated 01/17/07
Engineers Certification dated 08-17-12**

Dear Mr. Goodwin,

Based upon your Engineer's Certification submitted on 08/17/2012, the above referenced plan is not adequate for Grading and Drainage Certification for Release of Financial Guaranty for the following reasons:

- Please remove the plywood covering the inlet on the north end of Pinzon Street and provide a detail for the wall section in this area.
- Please employ a better BMP for sediment control.
- Show the swale/berm that directs drainage away from the wall west of the inlet discussed above.

If you have any questions, you can contact me at 924-3986.

Sincerely,

Curtis A. Cherne, P.E.
Principal Engineer--Hydrology,
Development and Building Services

C: Marilyn Maldonado, COA# 773481
File

PO Box 1293

Albuquerque

NM 87103

www.cabq.gov